

We care about you and your safety.

Nos preocupamos por usted y su seguridad.

Please complete your **FREE** recall repair.

Complete su reparación **GRATUITA** de la llamada a revisión.



VEHICLE SAFETY TEAM

[FName] [LName] [Business_Name],

At General Motors, protecting your safety is our top priority. Your [Model Year1] [MAKE1] [MODEL1] VIN: [VIN1] is affected by the Driver Side Window Switch Safety Recall and it's important that you schedule this **FREE** recall repair.

Under certain conditions, liquid can enter the power window switches in these vehicles and cause corrosion, leading to high electrical resistance. High electrical resistance can cause the switch to heat up, smoke or melt, increasing the risk of fire and injury. Occupants may notice that the power window is malfunctioning or inoperative. Smoke or an odor from smoke or melting may also come from the door panel.

We're here to help. Your safety is very important to us. Most dealership service centers will remain open during the developing pandemic and are available to complete your recall repair. Please check with your preferred dealer for specific service hours. To learn more, visit **gm.com/coronavirus**.

CONTACT A DEALER
COMUNÍQUESE CON UN CONCESIONARIO

[DEALER NAME]
[DLR_ADDRESS1]
[DLR_CITY], [DEALER_STATE_PROV] [DLR_POSTAL_CODE]
[DLR_SERVICE_PHONE]

You can schedule your **FREE** repair at any one of our 4,100+ Chevrolet, Buick, GMC or Cadillac dealerships. To find another dealer, please visit **mycertifiedservice.com/dealer** or call **1-866-467-9700**.



[FName] [LName] [Business_Name],

En General Motors, la protección de su seguridad es nuestra máxima prioridad. Su [Model Year1] [MAKE1] [MODEL1] VIN: [VIN1] se incluye dentro de los vehículos afectados por la llamada a revisión de seguridad del conmutador del elevavidrios del lado del conductor y es importante que programe esta reparación **GRATUITA** de la llamada a revisión.

En algunas condiciones, puede ingresar líquido a los conmutadores de los elevavidrios eléctricos de estos vehículos y causar corrosión, lo que produce una alta resistencia eléctrica. La alta resistencia eléctrica puede causar que el conmutador se caliente, emane humo o se derrita, lo que aumenta el riesgo de incendio y lesiones. Es posible que los ocupantes se den cuenta de que el elevavidrios eléctrico falla o no funciona. El panel de la puerta también puede desprender humo u olor a humo o derretimiento.

Puede programar su reparación **GRATUITA** en cualquiera de nuestros más de 4100 concesionarios de Chevrolet, Buick, GMC o Cadillac. Para buscar otro concesionario, visite **mycertifiedservice.com/dealer** o llame al **1-866-467-9700**.



[Unique_ID] [Creative_Code] SI

GM | VEHICLE SAFETY TEAM

GM Vehicle Safety
PO Box 3047
Milwaukee WI 53201

PRESORTED
FIRST-CLASS MAIL
U.S. POSTAGE
PAID
GENERAL MOTORS

*****AUTO**MIXED AADC 450
[Unique_ID] [Creative_Code] CV-011676

[FName] [LName]
[Business_Name]
[Address]
[Address2]
[City], [State] [ZIP]

