

	TYPE	RECALL CODE	QUESTION	ANSWER
Lower Ball Joint Nuts	Safety Recall	40N4	What vehicles are included in Safety Recall 40N4?	Certain 2018 model year Volkswagen Tiguan vehicles.
			What is the safety concern for Safety Recall 40N4?	The nut holding the lower ball joint of the front wheel in each side may be loose or improperly torqued. A loose or improperly torqued ball joint nut can result in dislocation of the lower ball joint. This may cause steering, traction or other stability issues relating to the front wheels and increase the risk of a crash.
			What is the repair for Safety Recall 40N4?	
			When will the repair for Safety Recall 40N4 be available?	Repairs can be scheduled with your authorized Volkswagen dealer now. To schedule an appointment, click here. Contact VW Roadside Assistance at 1-800-411-6688 to have your vehicle towed for FREE to your nearest Volkswagen dealer for repair. DO NOT DRIVE YOUR VEHICLE. Your Volkswagen dealer will provide you with a loaner vehicle for FREE if needed.
			Are there any precautions I should take because my vehicle is part of Safety Recall 40N4?	DO NOT DRIVE YOUR VEHICLE. Contact VW Roadside Assistance at 1-800-411-6688 to have your vehicle towed for FREE to your nearest Volkswagen dealer for repair. Your Volkswagen dealer will provide you with a loaner vehicle for FREE if needed.