		RECALL		
	TYPE	CODE	QUESTION	ANSWER
				Certain 2015-2018 model year Volkswagen Golf and Golf SportWagen vehicles. To see if your Volkswagen is part of a recall, please enter your Vehicle Identification Number (VIN) into the VIN Lookup tool here or NHTSA.gov/recalls.
Shift Lever Micro Switch	Compliance Recall	37L5	What vehicles are included in Compliance Recall 37L5?	Your VIN is located on the lower left corner of your vehicle's windshield, on your vehicle's registration card, and it may also be shown on your vehicle insurance certificate.
			What is the concern for Compliance Recall 37L5?	Over time, a build-up of silicate on the shift lever micro switch contacts can make it possible to remove the key from the ignition switch without the shift lever being in the "P" Park position. This makes the vehicle noncompliant with 49 CFR 571.114 Standard No. 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in the "P" Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.
			What is the repair for Compliance Recall 37L5?	To correct this defect, your authorized Volkswagen dealer will install an additional switch and circuit board. The recall repair will be FREE. To schedule an appointment for this recall repair, click here.
			When will the repair for Compliance Recall 37L5 be available?	Parts are available now and repairs have begun. Please contact your local Volkswagen Dealership to schedule an appointment. If you are not familiar with one, please click here to locate a Volkswagen Dealer near you.
			Are there any precautions I should take because my vehicle is part of Compliance Recall 37L5?	Yes. If this condition is present in the vehicle, an audible warning sound and failure message may appear in the instrument cluster. If this happens, owners are advised to contact an authorized Volkswagen dealer immediately and make arrangements to have the vehicle serviced.