

	TYPE	RECALL CODE	QUESTION	ANSWER
Shift Lever Micro Switch	Compliance Recall	37L5	What vehicles are included in Compliance Recall 37L5?	Certain 2015-2018 model year Volkswagen Golf and Golf SportWagen vehicles.
			What is the concern for Compliance Recall 37L5?	Over time, a build-up of silicate on the shift lever micro switch contacts can make it possible to remove the key from the ignition switch without the shift lever being in the "P" Park position. This makes the vehicle noncompliant with 49 CFR 571.114 Standard No. 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in the "P" Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.
			What is the repair for Compliance Recall 37L5?	When parts become available, dealers will install an additional switch and circuit board. The recall repair will be FREE.
			When will the repair for Compliance Recall 37L5 be available?	This recall repair is not yet available.
			Are there any precautions I should take because my vehicle is part of Compliance Recall 37L5?	Yes. If this condition is present in the vehicle, an audible warning sound and failure message may appear in the instrument cluster. If this happens, owners are advised to contact an authorized Volkswagen dealer immediately and make arrangements to have the vehicle serviced.
			How will I know when I can get my vehicle fixed under Compliance Recall 37L5?	Volkswagen will send you a letter via first-class mail when the recall repair is available for your vehicle. Until then, if you have any questions or vehicle concerns, please click here to find a Volkswagen dealer or click here to Contact Us.