

TOPIC	TYPE	RECALL CODE	QUESTION	ANSWER
HVAC Drain Tube/Airbag Control Module	Safety Recall	87F9	What vehicles are included in Safety Recall 87F9?	Certain 2018 model year Volkswagen Atlas vehicles.
			What is the safety concern for Safety Recall 87F9?	In certain vehicles, an air conditioning evaporator (HVAC) drain tube may have been twisted during vehicle assembly. If this tube is twisted, it can lead to water draining inside the passenger compartment and also onto the airbag control module. If the airbag control module gets wet, it can malfunction and possibly lead to an unintended airbag deployment. An unintended airbag deployment can cause injuries to vehicle occupants and possibly lead to a crash.
			What is the repair for Safety Recall 87F9?	The HVAC drain tube will be inspected on all affected vehicles. If a twisted tube is found, the hose as well as the airbag control module will be replaced. A subset of affected vehicles (that our records show have had a twisted drain tube replaced in the past) will have the airbag control module replaced under this recall. The recall repair will be FREE.
			When will the repair for Safety Recall 87F9 be available?	Parts are available now and repairs have begun. Please contact your local Volkswagen Dealership to schedule an appointment. If you are not familiar with one, please click here to locate a Volkswagen Dealer near you.
			Are there any precautions I should take because my vehicle is part of Safety Recall 87F9?	If this condition is present in your vehicle, you may notice wet carpet, a foul odor in the interior of the vehicle or the airbag warning lamp may illuminate. Other warning lights may also illuminate depending on vehicle equipment and conditions. If any of this happens, contact an authorized Volkswagen dealer without delay and arrange to have the vehicle inspected. Please click here to find a Volkswagen dealer