

SERVICE ENGINEER REPORT

Contact Date : 10/2/18 Time : NA
Pre Booked Date : NA Time : NA
Job/Campaign Number: NA

Service Centre : Eureka Recycling ^{minneapolis MN}
Engineers name : Joe McGlopin
Engineers Signature: [Signature]

VOR	<input checked="" type="checkbox"/> WARRANTY	CHARGEABLE	OTHER
-----	--	------------	-------

Customer: <u>Eureka Recycling</u> <u>minneapolis MN</u>	Time		Hours
	Travel start	<u>NA</u>	
On Site	<u>NA</u>		<u>NA</u>
Off Site			
Travel end	<u>NA</u>		<u>NA</u>
Order No: <u>NA</u>	Mileage	<u>NA</u>	Total hrs <u>NA</u>

Registration	VIN	1D92BEG31MF791003	Odometer	5281.1	Engine hrs	<u>NA</u>
--------------	-----	-------------------	----------	--------	------------	-----------

Defects Reported: Replace center dash panel - 2yr. old switch will rotate and become unplugged.

Repairs carried out including relevant fault codes: Replace center dash panel

Part Number	Qty	Description	Part Number	Qty	Description
	<u>1</u>	<u>Center dash panel</u>			

Customer Name & Signature of satisfaction: Matt Corlee Eureka Recycling Date: 10/6/18

SERVICE ENGINEER REPORT

Contact Date: 10/2/18 Time: NA Service Centre: WCA Hwy 6 Houston TX
 Pre Booked Date: NA Time: NA Engineers name: [Signature]
 Job/Campaign Number: _____ Engineers Signature: [Signature]

VOR	<input checked="" type="checkbox"/> WARRANTY	CHARGEABLE	OTHER
-----	--	------------	-------

Customer:		Time	Hours
<u>WCA at Texas</u>	Travel start	<u>NA</u>	<u>NA</u>
<u>509C TOWN</u>	On Site	<u>NA</u>	<u>NA</u>
	Off Site		
	Travel end	<u>NA</u>	<u>NA</u>
Order No: <u>NA</u>	Mileage	<u>NA</u>	Total hrs <u>NA</u>

Registration	VIN	1D9213GC13214F791002	Odometer	12321	Engine hrs	<u>NA</u>
--------------	-----	----------------------	----------	-------	------------	-----------

Defects Reported: Replace ignition switch bezel, bezel allows switch to rotate in housing and become unplugged

Repairs carried out including relevant fault codes: Replace bezel and install new lock plate

Part Number	Qty	Description	Part Number	Qty	Description
<u>821281</u>	<u>1</u>	<u>Ignition Bezel</u>			

Customer Name & Signature of satisfaction: 509C TOWN WCA Houston TX Date: 10/5/18

SERVICE ENGINEER REPORT

Contact Date: 10/2/18 Time: 1300 hrs Service Centre: 3rd Floor in the Center 3rd Floor
 Pre Booked Date: NA Time: NA Engineers name: [Signature]
 Job/Campaign Number: NA Engineers Signature: [Signature]

VOR	<input checked="" type="checkbox"/> WARRANTY	<input type="checkbox"/> CHARGEABLE	<input type="checkbox"/> OTHER
-----	--	-------------------------------------	--------------------------------

Customer:		Time	Hours
<u>Dennis Eagle Inc</u>	Travel start	<u>NA</u>	<u>NA</u>
	On Site	<u>NA</u>	<u>NA</u>
	<u>Off Site</u>		
	Travel end	<u>NA</u>	<u>NA</u>
Order No:	Mileage	<u>NA</u>	Total hrs <u>NA</u>

Registration	VIN	1D92B6C3B6KF741064	Odometer	18	Engine hrs	<u>NA</u>
--------------	-----	--------------------	----------	----	------------	-----------

Defects Reported: Replace ignition switch bezel. Ignition switch bezel
allows ignition switch to rotate in housing and become unplugged


Repairs carried out Including relevant fault codes: Replace ignition switch bezel and
install new lock plate to bezel

Part Number	Qty	Description	Part Number	Qty	Description
<u>821 282</u>	<u>1</u>	<u>ignition switch bezel</u>			

Customer Name & Signature of satisfaction: Dennis Eagle Inc [Signature] Date: 10/4/18

SERVICE ENGINEER REPORT

Contact Date: 10/2/18 Time: 1300
 Pre Booked Date: NA Time: _____
 Job/Campaign Number: NA

Service Centre: ECVA Gordon Lane
 Engineers name: Joe McLaughlin
 Engineers Signature: 

VOR	<input checked="" type="checkbox"/> WARRANTY	CHARGEABLE	OTHER
-----	--	------------	-------


Customer:		Time	Hours
<u>ECVA</u>	Travel start	<u>NA</u>	<u>NA</u>
<u>3030 Gordon Lane Sarasota FL</u>	On Site	<u>NA</u>	<u>NA</u>
	Off Site	<u>Sarasota FL</u>	<u>NA</u>
	Travel end	<u>NA</u>	<u>NA</u>
Order No:	Mileage	<u>7002</u>	Total hrs <u>NA</u>

Registration	<u>NA</u>	VIN	<u>1D92B6C18HF79061</u>	Odometer	<u>7912.6</u>	Engine hrs	<u>NA</u>
--------------	-----------	-----	-------------------------	----------	---------------	------------	-----------

Defects Reported: Replace Zgarlin switch bezel, Zgarlin switch bezel allows switch to rotate in housing and become unplugged

Repairs carried out including relevant fault codes: Replace Zgarlin switch bezel with new one and install new lock ring on bezel

Part Number	Qty	Description	Part Number	Qty	Description
<u>821 282</u>	<u>1</u>	<u>Zgarlin switch bezel</u>			

Customer Name & Signature of satisfaction: 

Willie McGrady
ECVA

Date: 10/3/18

SERVICE ENGINEER REPORT

Contact Date: 10/2/18 Time: 1300

Service Centre: ECVA Godwin Lane

Pre Booked Date: NA Time: NA

Engineers name: Joe McGillip

Job/Campaign Number: NA

Engineers Signature: 

VOR	<input checked="" type="checkbox"/> WARRANTY	CHARGEABLE	OTHER
-----	--	------------	-------


Customer:		Time	Hours
<u>ECVA</u>	Travel start	<u>NA</u>	<u>NA</u>
<u>3050 Godwin Lane Passaic NJ</u>	On Site	<u>NA</u>	<u>NA</u>
	<u>Off Site</u>	<u>Passaic NJ</u>	
	Travel end	<u>NA</u>	<u>NA</u>
Order No: <u>NA</u>	Mileage <u>NA</u>	<u>NA</u>	Total hrs <u>NA</u>

Registration	<u>NA</u>	VIN	<u>SEGLAD BC91140224</u>	Odometer	<u>8312.2</u>	Engine hrs	<u>NA</u>
--------------	-----------	-----	--------------------------	----------	---------------	------------	-----------

Defects Reported: Recall for Ignition Switch bezel, ignition switch contacts in housing, and becomes unplugged

Repairs carried out Including relevant fault codes:
Replace Ignition Switch Bezel with new one and install new lock ring on bezel

Part Number	Qty	Description	Part Number	Qty	Description
<u>821282</u>	<u>1</u>	<u>ignition switch bezel</u>			

Customer Name & Signature of satisfaction:  ECVA Willie McGrady Date: 10/3/18