

IMPORTANT SAFETY RECALL REMINDER FUEL PUMP O-RING



SUZUKI MOTOR OF AMERICA, INC.
3251 E. Imperial Highway
P.O. Box 1100, Brea CA 92822-1100



Recall Campaign EF

Presorted
First Class Mail
U.S. Postage
PAID
Permit No. 100
Gardena, CA



##

1

OFFICIAL RECALL INFORMATION
DO NOT IGNORE OR DISCARD

IMPORTANT SAFETY RECALL REMINDER

FIRST REMINDER - ACTION REQUIRED

WHY HAVE YOU RECEIVED THIS NOTICE?

Our records indicate that you are the owner of a motorcycle that is subject to a recall campaign that has still not been repaired.

This isn't junk mail. We urge you to take action to ensure efficiency of your motorcycle and it's operation.

THE FUEL PUMP O-RING ON CERTAIN **2017-2018 DL650A/XA**, **2018 GSX-S750/ZA** AND **2017-2018 GSX-R1000/A/R/Z** MOTORCYCLES MAY HAVE BECOME TWISTED DURING THE INSTALLATION PROCESS. THIS CAN REDUCE SEALING PERFORMANCE, WHICH CAN CAUSE A FUEL LEAK.

WHAT SHOULD YOU DO?

- Contact your nearest Suzuki Dealer
- Provide the Vehicle Identification Number (VIN) from the front of this card
- Schedule this ***FREE*** repair

Thank you for being a Suzuki customer.

Suzuki Motor of America, Inc.
Service Division



Scan the QR code or visit our website for more information and to find the dealer nearest you.

www.suzukicycles.com

