

## T-18-04 CONSUMER EMAIL

### Body

Dear Polaris Slingshot Owner,

Our records indicate that you are the owner of a Slingshot affected by Safety Recall **T-18-04** that was announced on December 17<sup>th</sup>, 2018.

Polaris has identified a concern with the backup camera assembly on some Slingshot models. The backup camera could fail internally and melt the voltage regulator over-mold. The circuit fuse may blow, which would inhibit proper tail light function. A letter will arrive at your address by postal mail that provides more information about the update and what you should do next.

Visit our [On-Road Safety Recall](#) page to verify if your Slingshot is impacted by this recall. Your local POLARIS dealer can be found on our [Dealer Locator](#) page. Contact your dealer to schedule a service appointment or complete a transfer of ownership if you no longer own the vehicle.

While your dealer is in the best position to answer your questions, you can also call our Customer Service department at **1-855-863-2284** to speak with a representative.

Sincerely,

Polaris Service