

**Recall Quarterly Report****19V-686**

**Manufacturer Name :** Daimler Trucks North America, LLC  
**NHTSA Recall No. / MFR Recall No. :** 19V-686 /FL-828  
**Recall Subject :** Insufficiently Tightened Flex Plate Fasteners  
**Owner Notification Beginning Date :** NOV 19, 2019  
**Owner Notification End Date:** NOV 19, 2019



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
7	JUL 28, 2021	2021-2	618	556	0	1
6	APR 14, 2021	2021-1	618	533	0	1
5	JAN 20, 2021	2020-4	618	528	0	1
4	OCT 23, 2020	2020-3	618	515	0	0
3	JUL 29, 2020	2020-2	618	467	0	1
2	APR 28, 2020	2020-1	618	309	0	0
1	JAN 28, 2020	2019-4	618	99	0	0

This Document Last Updated : AUG 11, 2021

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.