

**Recall Quarterly Report****19V-768**

**Manufacturer Name :** Mercedes-Benz USA, LLC  
**NHTSA Recall No. / MFR Recall No. :** 19V-768 /2019100018  
**Recall Subject :** Rear Axle Carrier Bolt Connection May Fail  
**Owner Notification Beginning Date :** NOV 22, 2019  
**Owner Notification End Date:** NOV 22, 2019



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
5	JAN 14, 2021	2020-4	36	31	0	0
4	OCT 16, 2020	2020-3	36	30	0	0
3	JUL 16, 2020	2020-2	36	29	0	0
2	APR 17, 2020	2020-1	36	25	0	0
1	JAN 13, 2020	2019-4	36	16	0	0

This Document Last Updated : JAN 22, 2021

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.