

Part 573 Safety Recall Report

19V-091

Manufacturer Name : Autocar, LLC**Submission Date :** FEB 15, 2019**NHTSA Recall No. :** 19V-091**Manufacturer Recall No. :** ACX-1903**Manufacturer Information :**

Manufacturer Name : Autocar, LLC

Address : 551 S WASHINGTON STREET
HAGERSTOWN IN 47346

Company phone : 765-489-5499

Population :

Number of potentially involved : 260

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2008-2019 Autocar Xpeditor

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : An engineering error resulted in an incorrect brake chamber size specification.

Production Dates : APR 18, 2008 - JAN 26, 2019

VIN Range 1 : Begin : 5VCA3LJF98H207650 End : 5VCA3RAF6LC230313 Not sequential**Description of Noncompliance :**

Description of the Noncompliance : Undersized air brake chamber can result in truck roll away under parking conditions due to reduced braking force. Noncompliance reference: CFR 49.393.41.B and FMVSS 571.121 S5.6.1

FMVSS 1 : 121 - Air brake systems

FMVSS 2 : NR

Description of the Safety Risk : Undersized air brake chamber can result in truck roll away under parking conditions due to reduced braking force.

Description of the Cause : An engineering error resulted in an incorrect brake chamber size specification.

Identification of Any Warning that can Occur : None

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR
NR
Country : NR

Chronology :

January 25,2019 During an internal configuration review a concern was raised regarding this configuration and as a result an internal investigation was launched. January 29,2019 The initial investigation was concluded.
February 8,2019 Upon review of all data compiled, Autocar decides perform a safety recall.

Description of Remedy :

Description of Remedy Program : The parking brake chambers will be replaced with the properly sized chambers at no cost to the owner.

How Remedy Component Differs from Recalled Component : The replacement parking brake chambers are larger and have a greater capacity.

Identify How/When Recall Condition was Corrected in Production : January 29, 2019 all bill of materials associated with this configuration have been blocked and all units in stock are re-worked to include the larger brake chambers.

Recall Schedule :

Description of Recall Schedule : Notification to begin April 15, 2019 and end April 16, 2019.

Planned Dealer Notification Date : APR 15, 2019 - APR 16, 2019

Planned Owner Notification Date : APR 15, 2019 - APR 16, 2019

* NR - Not Reported