

# Part 573 Safety Recall Report

# 19V-182

**Manufacturer Name :** Honda (American Honda Motor Co.)**Submission Date :** MAR 22, 2019**NHTSA Recall No. :** 19V-182**Manufacturer Recall No. :** U40,M45,O41,G44**Manufacturer Information :**

Manufacturer Name : Honda (American Honda Motor Co.)

Address : 1919 Torrance Blvd.

Torrance CA 90501

Company phone : 1-888-234-2138

**Population :**

Number of potentially involved : 1,101,534

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2013-2013 Acura RDX

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 433.

Production Dates : FEB 28, 2012 - MAR 28, 2013

VIN Range 1 : Begin : NR

End : NR

 Not sequential

Vehicle 2 : 2014-2014 Acura RDX

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The

number of affected units is 301.

Production Dates : APR 02, 2013 - MAR 31, 2014

VIN Range 1 : Begin : NR End : NR

Not sequential

Vehicle 3 : 2015-2015 Acura RDX

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 214.

Production Dates : APR 01, 2014 - APR 10, 2015

VIN Range 1 : Begin : NR End : NR

Not sequential

Vehicle 4 : 2016-2016 Acura RDX

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 6.

Production Dates : MAY 21, 2015 - FEB 03, 2016

VIN Range 1 : Begin : NR End : NR

Not sequential

Vehicle 5 : 2002-2002 Acura 3.2TL

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that

received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 17,948.

Production Dates : DEC 06, 2000 - FEB 01, 2002

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 6 : 2003-2003 Acura 3.2TL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 31,581.

Production Dates : DEC 04, 2001 - SEP 15, 2003

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 7 : 2009-2009 Acura TL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 790.

Production Dates : AUG 14, 2008 - JUN 04, 2009

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 8 : 2010-2010 Acura TL

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 869.

**Production Dates :** AUG 31, 2009 - AUG 30, 2010

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

**Vehicle 9 :** 2011-2011 Acura TL

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 246.

**Production Dates :** SEP 01, 2010 - FEB 24, 2011

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

**Vehicle 10 :** 2012-2012 Acura TL

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 663.

Production Dates : FEB 17, 2011 - SEP 04, 2012

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 11 : 2013-2013 Acura TL

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 420.

Production Dates : SEP 04, 2012 - AUG 02, 2013

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 12 : 2014-2014 Acura TL

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 142.

Production Dates : SEP 05, 2013 - MAR 06, 2014

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 13 : 2010-2010 Acura ZDX

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a

replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 64.

Production Dates : NOV 12, 2009 - JUL 29, 2010

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 14 : 2011-2011 Acura ZDX

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 15.

Production Dates : SEP 23, 2010 - MAR 30, 2011

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 15 : 2012-2012 Acura ZDX

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 21.

Production Dates : AUG 11, 2011 - JUN 21, 2012

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 16 : 2013-2013 Acura ZDX

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 3.

**Production Dates :** DEC 11, 2012 - MAR 01, 2013

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

**Vehicle 17 :** 2001-2001 Honda Accord

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 95,679.

**Production Dates :** JUL 04, 2000 - AUG 15, 2001

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

**Vehicle 18 :** 2002-2002 Honda Accord

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 118,722.

**Production Dates :** JUN 12, 2001 - SEP 19, 2002

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 19 : 2003-2003 Honda Accord

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 96,304.

Production Dates : JUN 06, 2002 - SEP 23, 2003

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 20 : 2004-2004 Honda Accord

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 84,137.

Production Dates : JUL 08, 2003 - AUG 30, 2004

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 21 : 2005-2005 Honda Accord

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D



inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 86,956.

Production Dates : JUN 18, 2004 - AUG 31, 2005

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 22 : 2006-2006 Honda Accord

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 86,581.

Production Dates : AUG 10, 2005 - SEP 01, 2006

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 23 : 2007-2007 Honda Accord

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 117,410.

Production Dates : JUN 07, 2006 - AUG 28, 2007

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 24 : 2001-2001 Honda Civic

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 38,268.

**Production Dates :** JUN 28, 2000 - SEP 10, 2001

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

**Vehicle 25 :** 2002-2002 Honda Civic

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 42,107.

**Production Dates :** AUG 02, 2001 - SEP 10, 2002

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

**Vehicle 26 :** 2003-2003 Honda Civic

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 26,322.

**Production Dates :** AUG 06, 2002 - SEP 11, 2003

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

Vehicle 27 : 2004-2004 Honda Civic

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 20,145.

**Production Dates :** JUL 24, 2003 - SEP 01, 2004

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

Vehicle 28 : 2005-2005 Honda Civic

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 21,891.

**Production Dates :** AUG 12, 2004 - SEP 02, 2005

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

Vehicle 29 : 2002-2002 Honda CR-V

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a

future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 625.

Production Dates : OCT 02, 2001 - SEP 25, 2002

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 30 : 2003-2003 Honda CR-V

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 619.

Production Dates : SEP 09, 2002 - SEP 02, 2003

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 31 : 2004-2004 Honda CR-V

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 398.

Production Dates : SEP 02, 2003 - SEP 06, 2004

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 32 : 2005-2005 Honda CR-V

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on dealership warranty, repair order,

**Descriptive Information :** and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 167.

**Production Dates :** AUG 30, 2004 - SEP 02, 2005

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

**Vehicle 33 :** 2006-2006 Honda CR-V

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 111.

**Production Dates :** AUG 02, 2005 - JUL 27, 2006

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

**Vehicle 34 :** 2007-2007 Honda CR-V

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 338.

**Production Dates :** JUL 27, 2006 - AUG 21, 2007

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

Vehicle 35 : 2010-2010 Honda CR-V

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 1,418.

**Production Dates :** AUG 21, 2009 - OCT 02, 2010

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

Vehicle 36 : 2011-2011 Honda CR-V

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 1,639.

**Production Dates :** AUG 02, 2010 - DEC 02, 2011

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

Vehicle 37 : 2003-2003 Honda Element

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015

Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 267.

Production Dates : NOV 19, 2002 - DEC 08, 2003

VIN Range 1 : Begin : NR End : NR

Not sequential

Vehicle 38 : 2004-2004 Honda Element

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 185.

Production Dates : DEC 02, 2003 - NOV 30, 2004

VIN Range 1 : Begin : NR End : NR

Not sequential

Vehicle 39 : 2005-2005 Honda Element

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 42.

Production Dates : JAN 05, 2005 - OCT 13, 2005

VIN Range 1 : Begin : NR End : NR

Not sequential

Vehicle 40 : 2006-2006 Honda Element

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that

could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 31.

Production Dates : OCT 26, 2005 - JUL 22, 2006

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 41 : 2007-2007 Honda Element

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 15.

Production Dates : OCT 11, 2006 - MAR 27, 2007

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 42 : 2008-2008 Honda Element

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 21.

Production Dates : JUN 22, 2007 - SEP 19, 2008

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 43 : 2009-2009 Honda Element



Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 6.

**Production Dates :** JAN 13, 2009 - JUL 31, 2009

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

**Vehicle 44 :** 2010-2010 Honda Element

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 15.

**Production Dates :** OCT 27, 2009 - OCT 07, 2010

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

**Vehicle 45 :** 2011-2011 Honda Element

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The

number of affected units is 6.

Production Dates : OCT 20, 2010 - FEB 22, 2011

VIN Range 1 : Begin : NR End : NR

Not sequential

Vehicle 46 : 2007-2007 Honda Fit

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 1.

Production Dates : APR 19, 2007 - APR 19, 2007

VIN Range 1 : Begin : NR End : NR

Not sequential

Vehicle 47 : 2002-2002 Honda Odyssey

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 49,966.

Production Dates : JUL 31, 2001 - AUG 23, 2002

VIN Range 1 : Begin : NR End : NR

Not sequential

Vehicle 48 : 2003-2003 Honda Odyssey

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that

received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 62,491.

Production Dates : AUG 15, 2002 - AUG 25, 2003

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 49 : 2004-2004 Honda Odyssey

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 55,991.

Production Dates : AUG 20, 2003 - AUG 13, 2004

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 50 : 2003-2003 Honda Pilot

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 813.

Production Dates : APR 15, 2002 - AUG 19, 2003

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 51 : 2004-2004 Honda Pilot

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 399.

**Production Dates :** AUG 20, 2003 - SEP 02, 2004

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

**Vehicle 52 :** 2005-2005 Honda Pilot

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 130.

**Production Dates :** SEP 07, 2004 - AUG 26, 2005

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

**Vehicle 53 :** 2006-2006 Honda Pilot

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 132.

Production Dates : AUG 16, 2005 - AUG 10, 2006

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 54 : 2007-2007 Honda Pilot

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 117.

Production Dates : AUG 02, 2006 - JUN 18, 2007

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 55 : 2008-2008 Honda Pilot

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 72.

Production Dates : JUN 19, 2007 - APR 02, 2008

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 56 : 2006-2006 Honda Ridgeline

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a

replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 63.

Production Dates : JAN 18, 2005 - MAY 31, 2006

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 57 : 2007-2007 Honda Ridgeline

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 760.

Production Dates : JUN 05, 2006 - JUN 05, 2007

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 58 : 2008-2008 Honda Ridgeline

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 561.

Production Dates : JUN 04, 2007 - JUL 16, 2008

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 59 : 2009-2009 Honda Ridgeline

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 146.

**Production Dates :** JUL 21, 2008 - AUG 07, 2009

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

**Vehicle 60 :** 2010-2010 Honda Ridgeline

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 172.

**Production Dates :** AUG 14, 2009 - JUN 09, 2010

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

**Vehicle 61 :** 2011-2011 Honda Ridgeline

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 113.

**Production Dates :** JUN 15, 2010 - OCT 26, 2011

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 62 : 2012-2012 Honda Ridgeline

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 126.

Production Dates : NOV 03, 2011 - SEP 27, 2012

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 63 : 2013-2013 Honda Ridgeline

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 158.

Production Dates : SEP 26, 2012 - SEP 04, 2013

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 64 : 2014-2014 Honda Ridgeline

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D



inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 56.

Production Dates : SEP 23, 2013 - JUN 25, 2014

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 65 : 2003-2003 Acura 3.2CL

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 5,393.

Production Dates : DEC 06, 2001 - JUN 13, 2003

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 66 : 2013-2013 Acura ILX

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 233.

Production Dates : APR 23, 2012 - FEB 28, 2013

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 67 : 2014-2014 Acura ILX

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 134.

**Production Dates :** MAY 03, 2013 - MAY 30, 2014

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

**Vehicle 68 :** 2015-2015 Acura ILX

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 110.

**Production Dates :** JUN 16, 2014 - NOV 06, 2014

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

**Vehicle 69 :** 2016-2016 Acura ILX

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 38.

**Production Dates :** FEB 02, 2015 - AUG 18, 2015

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

Vehicle 70 : 2003-2003 Acura MDX

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 773.

**Production Dates :** SEP 19, 2002 - SEP 23, 2003

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

Vehicle 71 : 2004-2004 Acura MDX

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 731.

**Production Dates :** SEP 15, 2003 - SEP 24, 2004

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

Vehicle 72 : 2005-2005 Acura MDX

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a

future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 627.

Production Dates : SEP 16, 2004 - SEP 16, 2005

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 73 : 2006-2006 Acura MDX

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 565.

Production Dates : SEP 19, 2005 - AUG 30, 2006

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 74 : 2007-2007 Acura RDX

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 364.

Production Dates : JUN 28, 2006 - JUL 16, 2007

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 75 : 2008-2008 Acura RDX

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order,

**Descriptive Information :** and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 384.

**Production Dates :** JUL 18, 2007 - JUN 02, 2008

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

**Vehicle 76 :** 2009-2009 Acura RDX

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 126.

**Production Dates :** JUN 13, 2008 - JUL 13, 2009

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

**Vehicle 77 :** 2010-2010 Acura RDX

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 167.

**Production Dates :** JUL 20, 2009 - JUN 25, 2010

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

Vehicle 78 : 2011-2011 Acura RDX

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 158.

**Production Dates :** JUL 07, 2010 - AUG 02, 2011

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

Vehicle 79 : 2012-2012 Acura RDX

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 83.

**Production Dates :** AUG 08, 2011 - DEC 20, 2011

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

Vehicle 80 : 2013-2013 Acura ILX Hybrid

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015

Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 29.

Production Dates : APR 19, 2012 - DEC 06, 2012

VIN Range 1 : Begin : NR End : NR

Not sequential

Vehicle 81 : 2014-2014 Acura ILX Hybrid

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 3.

Production Dates : DEC 04, 2013 - FEB 25, 2014

VIN Range 1 : Begin : NR End : NR

Not sequential

Vehicle 82 : 2004-2004 Acura TL

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 1.

Production Dates : JUL 26, 2004 - JUL 26, 2004

VIN Range 1 : Begin : NR End : NR

Not sequential

Vehicle 83 : 2005-2005 Acura TL

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that

could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 1.

Production Dates : OCT 20, 2004 - OCT 20, 2004

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 84 : 2006-2006 Acura TL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 4.

Production Dates : OCT 25, 2005 - JUN 21, 2006

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 85 : 2009-2009 Honda Accord

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 3.

Production Dates : OCT 30, 2008 - APR 28, 2009

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 86 : 2004-2004 Honda Civic Hybrid



Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 6,265.

**Production Dates :** JUL 15, 2003 - JUL 28, 2004

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

**Vehicle 87 :** 2005-2005 Honda Civic Hybrid

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 7,924.

**Production Dates :** AUG 02, 2004 - AUG 06, 2005

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

**Vehicle 88 :** 2001-2001 Honda Civic NGV

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The

number of affected units is 173.

Production Dates : NOV 15, 2000 - JUL 26, 2001

VIN Range 1 : Begin : NR End : NR

Not sequential

Vehicle 89 : 2002-2002 Honda Civic NGV

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 195.

Production Dates : SEP 19, 2001 - JUL 18, 2002

VIN Range 1 : Begin : NR End : NR

Not sequential

Vehicle 90 : 2003-2003 Honda Civic NGV

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 115.

Production Dates : JAN 09, 2003 - AUG 08, 2003

VIN Range 1 : Begin : NR End : NR

Not sequential

Vehicle 91 : 2004-2004 Honda Civic NGV

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that

received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 257.

Production Dates : JUN 20, 2003 - AUG 19, 2004

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 92 : 2005-2005 Honda Civic NGV

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 205.

Production Dates : OCT 06, 2004 - JUL 27, 2005

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 93 : 2003-2003 Honda Civic Hybrid

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5D driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5D inflator). Similar vehicles not included in this recall either 1) were repaired with a driver's airbag inflator from an alternative manufacturer, 2) are scheduled for a future recall according to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, or 3) are currently subject to an open driver airbag inflator recall. The number of affected units is 10,065. Due to system error can't enter in correct production date range. Correct production date range is 02/19/2002 to 07/29/2003.

Production Dates : JAN 01, 1901 - JAN 01, 1901

VIN Range 1 : Begin :

NR

End : NR

Not sequential

**Description of Defect :**

Description of the Defect : A defect related to motor vehicle safety exists in certain vehicles with desiccated PSDI-5D inflators installed either as 1) final remedy parts for safety recalls of non-desiccated PSDI / PSDI-4 / PSDI-4K inflators installed as OEM equipment or 2) replacement service parts for vehicles involved in airbag deployed crashes. Higher than normal operating pressures have been observed in laboratory testing of parts returned from the field. In addition, one field over-pressurization incident that resulted in a ruptured PSDI-5D inflator has been confirmed. Inflator deployment resulting in higher than normal operating pressure may result in an inflator rupture.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : An inflator rupture may cause metal fragments to pass through the airbag and into the vehicle interior at high speed, which may result in injury or death to vehicle occupants.

Description of the Cause : NR

Identification of Any Warning  
that can Occur : NR**Supplier Identification :****Component Manufacturer**

Name : Takata

Address : 111 Peyerk Court  
Romeo, MI, USA FOREIGN STATES 48065

Country : Mexico

**Chronology :**

See attached chronology dated March 8, 2019.

**Description of Remedy :**

Description of Remedy Program : Registered owners of all affected vehicles will be contacted by mail and asked to take their vehicle to an Acura or Honda automobile dealer, as applicable. The dealer will replace the driver's airbag inflator with an inflator from an alternative manufacturer for free.  
Owners who have paid to have these repairs completed at their own expense will be eligible for reimbursement, according to the recall reimbursement plan on file with NHTSA.

How Remedy Component Differs from Recalled Component : Driver's airbag inflator kit, driver's airbag inflator kit, part number: 04770-S5A-305, 04770-SDA-305.

Driver's airbag module, driver's airbag module, part number: 06770-S0K-A30ZA, 06770-S0K-A30ZB, 06770-S0X-A30ZA, 06770-S0X-A40ZA, 06770-S5A-A30ZA, 06770-S5A-A40ZA, 06770-S84-A30ZA, 06770-S84-A30ZB, 06770-S84-A30ZC, 06770-S84-A30ZD, 06770-SDA-A30ZA, 06770-SDA-A30ZB, 06770-SDA-A40ZA, 06770-SDA-A40ZB, 77810-SDA-A20ZA, 77810-SDA-A20ZB, 77810-SJC-A81ZA, 77810-SJC-A91ZA, 77810-SJC-A91ZB, 77810-STK-A80ZA, 77810-STK-A90ZA, 77810-SWA-A70ZA, 77810-TK4-A80ZA, 77810-TV9-A80ZA, 77810-TX4-A81ZA, 77810-TX6-A80ZA

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : Dealer notification is expected to begin on or about March 7, 2019.  
Owner notification is expected to begin on or about April 17, 2019.

Planned Dealer Notification Date : MAR 07, 2019 - NR

Planned Owner Notification Date : APR 17, 2019 - NR

\* NR - Not Reported