

Part 573 Safety Recall Report

19V-194

Manufacturer Name : SVO GROUP INC

Submission Date : MAR 08, 2019

NHTSA Recall No. : 19V-194

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : SVO GROUP INC

Address : 2503 ADA DR

ELKHART IN 46514

Company phone : 5742959359

Population :

Number of potentially involved : 5

Estimated percentage with defect : NR

Vehicle Alterer Information :

Vehicle 1 : 2018-2018 FORD E-450

Descriptive Information : In regards to Morryde recall 18v367

Production Dates : MAR 16, 2018 - JUN 14, 2018

Description of Defect :

Description of the Defect : The u bolts installed over the rear axle hold the leaf springs and rear axle together. Insufficient torque on the u-bolts may cause the u-bolts to loosen or break resulting in the potential for the rear axle to break away from the chassis.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : This could lead to loss of control over the vehicle and pose danger to the vehicle operator and other motorists.

Description of the Cause : NR

Identification of Any Warning that can Occur : Only notification from Morryde

Supplier Identification :

Component Manufacturer

Name : MORRYDE INTERNATIONAL INC

Address : 1966 STERLING AVE

Elkhart INDIANA 46516

Country : United States

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs
from Recalled Component : NRIdentify How/When Recall Condition
was Corrected in Production : NR**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name :

Address :

Country :

Company Phone :

* NR - Not Reported