

Part 573 Safety Recall Report

19V-294

Manufacturer Name : Forest River, Inc.

Submission Date : APR 12, 2019

NHTSA Recall No. : 19V-294

Manufacturer Recall No. : 55-0992



Manufacturer Information :

Population :

Manufacturer Name : Forest River, Inc.

Number of potentially involved : 16

Address : 55470 CR 1

Estimated percentage with defect : 100 %

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

Vehicle Information :

Vehicle 1 : 2019-2019 Forest River Inc. Dynamax Isata

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : ISC30FWD - 5

ISC30FWD4X4 - 9

ISC35DBD - 1

ISC36DSD - 7

ISC36DSD4X4 - 3

Forest River identified the vehicles under FCA Recall 18V277 by using the VINs provided by FCA.

4-12-2019 - Updating Year, models and quantities affected

ISC30FWD - 3

ISC30FWD4X4 - 4

ISC35DBD - 1

1SC36DSD - 3

1SC36DSD4X4 - 3

Production Dates : FEB 21, 2018 - NOV 21, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : Per FCA recall notice 18V277: "Some primary and secondary brake tube hoses were produced with no anticorrosion plating on the ferrules. Anti-corrosion plating is required to meet FCA US LLC ("FCA US") long-term durability corrosion requirements. The absence of anti-corrosion plating on the brake tube hose ferrules may allow premature corrosion and subsequently can lead to a partial or complete loss of brake function.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Per FCA recall notice 18V277: The ferrules on both brake hoses, in certain circumstances, may prematurely corrode and develop a brake fluid leak simultaneously and potentially result in a partial or complete loss of brake function. Loss of brake function can cause vehicle crash without prior warning.

Description of the Cause : Per FCA recall notice 18V277: None Provided

Identification of Any Warning that can Occur : Per FCA recall notice 18V277: None Provided

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

On April 8, 2019 Forest River's Office of Corporate Compliance received FCA's recall notice containing the VINs affected under FCA Recall Number 18V277. The same day an investigation to identify the involved vehicles was completed.

It is Forest River's understanding that FCA will facilitate all quarterly reporting requirements to NHTSA.

On April 12, 2019, Forest River's Corporate Committee will be advised of the recall.

On April 12, 2019 during a review of the VINs affected it was determined that a clerical error was made during the population ID. amended to reflect only 16 vehicles are affected.

Description of Remedy :

Description of Remedy Program : Forest River will provide a copy of the recall notification to Owners and Dealers. Owners and Dealers will be instructed to make an appointment with any FCA Dealership to have the recall remedied.

What is the FCA Customer Service Phone Number? (800) 853-1403
What is the Forest River Customer Service Phone Number? (574) 262-3474

How Remedy Component Differs from Recalled Component : Per FCA recall notice 18V277: Part Name: TUBE ASSEMBLY - BRAKE / TUBE ASSEMBLY - BRAKE
Part Description: Master Cylinder to HCU, Primary / Master Cylinder to HCU, Secondary Part Number: 68226109AC / 68226110AC

Identify How/When Recall Condition was Corrected in Production : Per FCA recall notice 18V277: None Provided

Recall Schedule :

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : MAY 21, 2019 - MAY 21, 2019

Planned Owner Notification Date : MAY 21, 2019 - MAY 21, 2019

* NR - Not Reported