

Part 573 Safety Recall Report

19V-343

Manufacturer Name : Suzuki Motor of America, Inc.

Submission Date : MAY 02, 2019

NHTSA Recall No. : 19V-343

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Suzuki Motor of America, Inc.

Address : 3251 East Imperial Highway

Brea CA 92821-6795

Company phone : 714-996-7040

Population :

Number of potentially involved : 21,052

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2010-2013 Suzuki Kizashi

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : The recall population was determined based on production records. All 2010-2013 model year vehicles are included.

Production Dates : OCT 13, 2009 - OCT 31, 2012

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : The front passenger seat occupant classification system (OCS) may misclassify adult occupants as child occupants and suppress the front air bag due to the seating posture/position of the adult occupant.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : In a crash necessitating air bag deployment, the front air bag may not deploy with an adult occupant in the front passenger seat, increasing the risk of injury to the adult occupant.

Description of the Cause : NR

Identification of Any Warning that can Occur : When the front passenger front air bag is suppressed, the PASS AIR BAG OFF indicator will be illuminated.

Supplier Identification :

Component Manufacturer

Name : Continental
Address : NR
NR
Country : NR

Chronology :

The chronology is attached as a separate document.

Description of Remedy :

Description of Remedy Program : Suzuki has not yet determined a remedy. Suzuki will notify NHTSA through an amended Part 573 report when a remedy has been determined. Suzuki Motor of America, Inc.'s plan for reimbursing owners who have paid for repairs to remedy the reported condition in advance of recall notification is attached as a separate document.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Suzuki has not yet decided a recall notification schedule, but will mail owner notification letters no more than 60 days from the date of submission of this report. Suzuki will notify NHTSA through an amended Part 573 report when a notification schedule has been decided.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported