

Part 573 Safety Recall Report

19V-603

Manufacturer Name : Jaguar Land Rover North America, LLC**Submission Date :** SEP 13, 2019**NHTSA Recall No. :** 19V-603**Manufacturer Recall No. :** N367**Manufacturer Information :****Population :**

Manufacturer Name : Jaguar Land Rover North America, LLC

Number of potentially involved : 14,277

Address : 100 Jaguar Land Rover Way

Estimated percentage with defect : 100 %

Mahwah NJ 07495

Company phone : 8188500

Vehicle Information :

Vehicle 1 : 2018-2018 LAND ROVER RANGE ROVER SPORT

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : NR

Descriptive Information : Certain 2018 Model Year Range Rover Sport vehicles, equipped with the Continental Surround Camera System, where the system may fail to display the rearview image when a vehicle is about to reverse or is reversing.

Production Dates : JUL 12, 2017 - JUL 03, 2018

VIN Range 1 : Begin : SALWR2RV1JA400003 End : SALWR2RV8JA414769

 Not sequential

VIN Range 2 : Begin : SALWR2RK5JA695614 End : SALWR2RV0JA699970

 Not sequential

VIN Range 3 : Begin : SALWR4RY1JA162191 End : SALWR2RE9JA199970

 Not sequential

VIN Range 4 : Begin : SALWV2RE3JA800012 End : SALWR2RE9JA813920

 Not sequential

Vehicle 2 : 2018-2018 LAND ROVER RANGE ROVER

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : NR

Descriptive Information : Certain 2018 Model Year Range Rover vehicles, equipped with the Continental Surround Camera System, where the system may fail to display the rearview image when a vehicle is about to reverse or is reversing.

Production Dates : JUL 05, 2017 - JUL 03, 2018

VIN Range 1 : Begin : SALGS4RY6JA361214 End : SALGS5REXJA399959

 Not sequential

VIN Range 2 : Begin : SALGS2RE7JA500017 End : SALGS2RE1JA516164

 Not sequential

Description of Defect :

Description of the Defect : A concern has been identified on certain 2018 Model Year Range Rover and Range Rover Sport vehicles, equipped with the Continental Surround Camera System, where the system may fail to display the rearview image when a vehicle is about to reverse or is reversing.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Failure to display the rearview image will reduce the driver's visibility, and should the driver not check their surroundings appropriately, may increase the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Jaguar Land Rover Limited

Address : Abbey Road

Whitley, Coventry FOREIGN STATES CV34LF

Country : United Kingdom

Chronology :

See File "Recall N367 Chronology".

Description of Remedy :

Description of Remedy Program : Land Rover will notify owners, and authorized repairers will download the latest infotainment system software to the vehicle.

There will be no charge to owners for this repair.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Distribution of owner notification letters will occur on or before October 14, 2019. Notifications to dealers will occur on September 3, 2019.

Planned Dealer Notification Date : SEP 03, 2019 - SEP 03, 2019

Planned Owner Notification Date : OCT 14, 2019 - OCT 14, 2019

* NR - Not Reported