

Part 573 Safety Recall Report

19V-610

Manufacturer Name : Newmar Corporation

Submission Date : AUG 20, 2019

NHTSA Recall No. : 19V-610

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 376

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2020 Newmar Mountain Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the bedroom fascia header has potential to fall unexpectedly on top of the bed mattress. This has potential to cause harm/injury if a person is on the bed mattress. Correction: Newmar Dealer's will properly secure the loose fascia header.

Production Dates : DEC 12, 2016 - APR 04, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 2 : 2018-2020 Newmar Essex

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the bedroom fascia header has potential to fall unexpectedly on top of the bed mattress. This has potential to cause harm/injury if a person is on the bed mattress. Correction: Newmar Dealer's will properly secure the loose fascia header.

Production Dates : DEC 12, 2016 - APR 04, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 3 : 2018-2020 Newmar King Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the bedroom fascia header has potential to fall unexpectedly on top of the bed mattress. This has potential to cause harm/injury if a person is on the bed mattress. Correction: Newmar Dealer's will properly secure the loose fascia header.

header.

Production Dates : DEC 12, 2016 - APR 04, 2019

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : On certain motorhomes, the bedroom fascia header has potential to fall unexpectedly on top of the bed mattress. This has potential to cause harm/injury if a person is on the bed mattress. Correction: Newmar Dealer's will properly secure the loose fascia header.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : the bedroom fascia header has potential to fall unexpectedly on top of the bed mattress. This has potential to cause harm/injury if a person is on the bed mattress.

Description of the Cause : Not properly secured fascia header.

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Newmar

Address : 355 N. Delaware St.

Nappanee INDIANA 46550

Country : United States

Chronology :

On 8/14/2019, Newmar was notified by a Newmar dealer that a bedroom fascia header was discovered on the bed mattress. Today 8/20/2019, out of an abundance of caution, Newmar has decided to issue a safety recall. Correction: Screws and brackets will be added to properly secure the fascia header.

Description of Remedy :

Description of Remedy Program : Correction: Screws and brackets will be added to properly secure the fascia header.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : On or before 10/19/2019, owner/dealer letters will be mailed out.

Planned Dealer Notification Date : OCT 19, 2019 - OCT 19, 2019

Planned Owner Notification Date : OCT 19, 2019 - OCT 19, 2019

* NR - Not Reported