

Part 573 Safety Recall Report

19V-611

Manufacturer Name : Keystone RV Company**Submission Date :** AUG 21, 2019**NHTSA Recall No. :** 19V-611**Manufacturer Recall No. :** 19-359**Manufacturer Information :**

Manufacturer Name : Keystone RV Company

Address : PO Box 2000
2642 Hackberry Drive Goshen IN
46527

Company phone : 574-535-2100

Population :

Number of potentially involved : 67

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2019-2020 Keystone Hideout 25TH

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Hideout Toy Haulers

Production Dates : AUG 29, 2018 - JUN 12, 2019

VIN Range 1 : Begin : 4YDT25T26K7245684 End : 4YDT25T28K7248408

 Not sequential

VIN Range 2 : Begin : 4YDT25T27L7241080 End : 4YDT25T23L7241299

 Not sequential**Description of Defect :**

Description of the Defect : It has been determined that the vehicles in the recall population are missing the Special Transportation Provision warning label (AD-96) in the garage area as outlined in 6.4.6.9 of the 2018 NFPA 1192 code book.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Vehicles and equipment powered by internal combustion engines and placed in recreational vehicles can cause carbon monoxide poisoning or asphyxiation, which could result in death or serious injury. The flammable liquids used to power these items can cause a fire or explosion, which can result in death or serious injury.

Description of the Cause : The Special Transportation Provision label (AD-96) was overlooked in a new model.

Identification of Any Warning that can Occur : The Special Transportation Provision label (AD-96) was not placed on the wall inside of the garage area of the travel trailer.

Supplier Identification :**Component Manufacturer**

Name : NR
Address : NR
NR
Country : NR

Chronology :

7/30/2019 – Report made through Nebraska state inspectors that the Special Transportation Provision label (AD-96) was not installed on certain Toy Haulers. Investigation for range and scope opened.
8/1/2019 – Calls to dealers with stock units to verify labels throughout the range were missing.
8/19/2019 – Investigation concluded range and scope determined. Proceed with recall.

Description of Remedy :

Description of Remedy Program : The remedy is to mail the Special Transportation Provision warning label (AD-96) to dealers and customers in possession of the affected Travel Trailers to affix the labels in the garage area at no cost to them. Manufacturer Reimbursement Plan on file as of 10/25/2018. General reimbursement plan to be updated every two years. New vehicles are covered under warranty.

How Remedy Component Differs from Recalled Component : The Special Transportation Provision label (AD-96) will be added to the garage area as outlined in 6.4.6.9 of the 2018 NFPA 1192 code book.

Identify How/When Recall Condition was Corrected in Production : Units were quarantined, inspected then repaired as indicated by inspection.

Recall Schedule :

Description of Recall Schedule : Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA. Dealers will receive a letter which includes the repair instructions. No separate dealer repair procedures will be provided.

Planned Dealer Notification Date : SEP 20, 2019 - SEP 20, 2019
Planned Owner Notification Date : SEP 20, 2019 - SEP 20, 2019

* NR - Not Reported