

# Part 573 Safety Recall Report

# 19V-621

**Manufacturer Name :** Braxton Creek RV**Submission Date :** AUG 26, 2019**NHTSA Recall No. :** 19V-621**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Braxton Creek RV

Address : 0925 North State Rd. 5

Shipshewana IN 46565

Company phone : 768-7932

**Population :**

Number of potentially involved : 55

Estimated percentage with defect : 95 %

**Vehicle Information :**

Vehicle 1 : 2020-2020 Bushwhacker Bushwhacker

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

**Descriptive Information :** The Bushwhacker units manufactured between 5/01/19 and 7/31/19 may not have a LP/Co detector installed. Braxton Creek built 55 Bushwhacker trailers in that time frame. Any Bushwhacker that has been built after 7/31/19 has the LP/CO detector installed.

Production Dates : MAY 01, 2019 - JUL 31, 2019

VIN Range 1 : Begin : 7HFB1KB19L17X0050 End : 7HFB1KB13L17X0105  Not sequential**Description of Noncompliance :**

**Description of the Noncompliance :** Braxton Creek may not have installed LP/CO detectors in the Bushwhacker product.

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** Without the LP/CO detector the user of the RV could be at risk of carbon monoxide poisoning, a potentially life-threatening condition.

**Description of the Cause :** Using any gas appliance indoors can cause carbon monoxide to build up inside the RV.

**Identification of Any Warning that can Occur :** Carbon monoxide poisoning may include dull headache, weakness, dizziness, nausea or vomiting, shortness of breath, confusion, blurred vision or loss of consciousness.

## Supplier Identification :

### Component Manufacturer

Name : NR  
Address : NR  
NR  
Country : NR

## Chronology :

It was brought to our attention by one of our dealers the we at Braxton Creek had not installed a LP/CO detector in a Bushwhacker RV. Upon further investigation, we discovered that we may have multiple units in the field that do not have the required LP/CO detector installed.

## Description of Remedy :

Description of Remedy Program :	Because we may have failed to install LP/CO detectors, Braxton Creek will provide all our dealers and retail customers with a compliant plug-in 120 volt LP/Co detector with battery backup.
How Remedy Component Differs from Recalled Component :	There was no LP/CO detector installed therefore we will provide all customers with a Kidde Gas & Carbon Monoxide Alarm. Model # KN-COEG-3. Detectors will plug into a standard 120 volt receptacle with a 9 volt battery backup.
Identify How/When Recall Condition was Corrected in Production :	As soon as we were aware of the non-compliance Braxton Creek immediately started checking to confirm installation of LP/CO detectors in every Bushwhacker unit manufactured thereafter.

## Recall Schedule :

Description of Recall Schedule :	Braxton Creek will immediately begin notifying dealers and retail customers, of the need to install LP/CO leak detectors, and begin sending out detectors.
Planned Dealer Notification Date :	AUG 26, 2019 - SEP 27, 2019
Planned Owner Notification Date :	AUG 26, 2019 - SEP 27, 2019

\* NR - Not Reported