

Part 573 Safety Recall Report**19V-749****Manufacturer Name :** Collins Bus Corporation**Submission Date :** OCT 18, 2019**NHTSA Recall No. :** 19V-749**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Collins Bus Corporation

Address : P.O. Box 2946
Hutchinson KS 67504

Company phone : 9999

Population :

Number of potentially involved : 24

Estimated percentage with defect : NR

Vehicle Information :

Vehicle 1 : 2018-2019 Collins TL400, TL408, TH400 and TH408

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : Based on external audit, Collins Bus Corporation determined that the affected buses were limited to these models manufactured from May 1, 2018 to Sept 16, 2019. Once the noncompliance was discovered on October 14, 2019, procedures were modified to avoid the noncompliance and subsequent manufactured units do not contain the defect.

Production Dates : MAY 01, 2018 - SEP 16, 2019

VIN Range 1 : Begin : NR End : NR

 Not sequential**Description of Defect :**

Description of the Defect : This report serves as Collins Bus Corporation's notification to the U.S. Department of Transportation, National Highway Traffic Safety Administration, that a noncompliance with Federal Motor Vehicle Safety Standard 111 "Rear Visibility" exists in certain 2018 and 2019 Collins School Buses and MFSAB's manufacture after May 1 2018.

FMVSS 1 : 111 - Rearview mirrors

FMVSS 2 : NR

Description of the Safety Risk : Certain units under 10000 lbs were not manufactured with the rear camera**Description of the Cause :** NR**Identification of Any Warning** NR
that can Occur :

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

During an audit of a Collins MFSAB, Collins Engineering was contacted by NHSTA Safety Compliance Engineer informing that this unit was not manufactured with the backup camera. After researching the unit Collins found that we were not in compliance with FMVSS 111 rear image S6.2.

Collins review all orders with the GVWR 10000lbs. or less to find the population and to make sure that we are in compliance with the FMVSS 111.

Description of Remedy :

Description of Remedy Program : Customers will be instructed to take their vehicle to their Collins distributor where the vehicle will be repaired for this potential noncompliance. Detailed instructions will be provided for the installation of the backup camera. Collins Bus Corporation will provide these services to our customers at no charge. Any customer who has made repairs of this defect prior to this notice will be reimbursed the cost of those repairs.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : Collins review all orders with the GVWR 10000 lbs. or less to find the population and to make sure that we are in compliance with the FMVSS 111.

Recall Schedule :

Description of Recall Schedule : Collins Bus has verified that, as of October 14, 2019, production remedies were in place to prevent the noncompliance. Owner notifications and Dealer Notifications will be issued by November 11, 2019

Planned Dealer Notification Date : NOV 01, 2019 - NOV 06, 2019

Planned Owner Notification Date : NOV 06, 2019 - NOV 11, 2019

* NR - Not Reported