

Recall Annual Report**19V-869****Manufacturer Name :** Daimler Trucks North America, LLC**NHTSA Recall No. / MFR Recall No. :** 19V-869 /FL-841**Recall Subject :** Fan Hub Bolts Improperly Torqued**Owner Notification Beginning Date :** JAN 16, 2020**Owner Notification End Date:** JAN 16, 2020**Annual Reports**

Report #	Submission Date	Report Year	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	APR 25, 2023	2023	145	142	0	0

Quarterly Reports

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
8	JAN 27, 2022	2021-4	145	141	0	0
7	OCT 15, 2021	2021-3	145	141	0	0
6	JUL 28, 2021	2021-2	145	141	0	0
5	APR 14, 2021	2021-1	145	141	0	0
4	JAN 21, 2021	2020-4	145	139	0	0
3	OCT 23, 2020	2020-3	145	138	0	0
2	JUL 29, 2020	2020-2	145	125	0	0
1	APR 28, 2020	2020-1	145	98	0	0

This Document Last Updated : APR 25, 2023

Definitions :**Report Year :** The report year the manufacturer is reporting recall completion figures.**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).**Recall Population :** The total number of products recalled by the manufacturer.**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.**Total Removed :** Products that have been scrapped, stolen, or exported.