



5 Stan Perkins Road Spartanburg, South Carolina 29307 USA 864-327-4744
www.kymcousa.com

VOLUNTARY SAFETY RECALL

February 2019

NHTSA Recall# 19V037

Voluntary Safety Recall: KYMCO Like 150i, Potential leaking from the high-pressure electric fuel pump.

Dear KYMCO Dealer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Defect Involved:

Kwang Yang Motor Co., Ltd. (KYMCO) is voluntarily recalling all 2018 model year and select 2019 model year “Like 150i” units. The units have a high-pressure electric fuel pump that may leak fuel through the rubber plug around the electrical wiring inside the fuel pump when the fuel tank is overfilled, causing a potential fire hazard.

Vehicles Involved and VIN Range:

All 2018 model year & select 2019 model year Like 150i units (912 units total).

VIN Range of affected units:

2018 Model Year: LC2DBJ140JC100101 through LC2DBJ147JC100936

2019 Model Year: LC2DBJ149KC100101 through LC2DBJ147KC100176

Description of Defect:

The defect is due to potential fuel leaking through the rubber plug around the electrical wiring inside the fuel pump when the fuel tank is overfilled, causing a potential fire hazard.

Plan of Action:

KYMCO USA, Inc. will send the repair kits to all authorized KYMCO dealers based on the number of affected units purchased to ensure that each dealer has an adequate quantity of kits on hand to perform the recall procedure in a timely manner. Additional repair kits are available upon request by the dealer.



5 Stan Perkins Road Spartanburg, South Carolina 29307 USA 864-327-4744
www.kymcousa.com

KYMCO USA, Inc. will send letters to all registered owners (based off warranty registration with KYMCO USA, Inc.) of the affected units advising them of this voluntary recall and instructing them to make appointments for the repair of their vehicle at any authorized KYMCO dealer as soon as possible. Please schedule the repairs for the owners as soon as possible to prevent any risk as a result of this defect. We have included with this letter a list of customers who have been registered with KYMCO USA, Inc. by your dealership in our warranty system with affected Like 150i units. Please advise KYMCO USA, Inc. if there are any outstanding customers who have not been warranty registered so we can contact them immediately.

The repair kit (Part number: Like150-2019-Recall-Kit) contains the following items:

- Replacement Fuel Pump
- Repair Instructions
- Warranty/Reimbursement Instructions

Reimbursement for Recall:

KYMCO USA, Inc. will provide the recall repair kits free of charge and pay pre-established KYMCO dealer labor rates for each repair performed. If any required equipment/instrument is needed, that is not in dealers' possession, we will provide it to them free of charge. Kwang Yang Motor Co., Ltd. has assigned a flat rate code for this recall:

- Flat rate code: Like150-2019-Recall-Kit
- Flat rate time allocated: One (1) hour

For any further questions, please contact KYMCO USA, Inc.

Phone: (888) 622-0781

Email: like1502019recall@kymcousa.com

We apologize for any inconvenience caused by this voluntary recall.

Kindest regards,

KYMCO USA, Inc.