

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS5318
URGENT - DISTRIBUTE IMMEDIATELY

Date: February 6, 2020

Subject: N192278300 - Safety Recall
Front Seat Crossmember Improperly Welded
Revised Part Information and Service Procedure

Models: 2019 – 2020 Buick Regal

To: All General Motors Dealers

This bulletin is being revised with an updated part information table, service procedure and to add the customer letter. Please discard all previous copies of bulletin N192278300.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS