

From: [REDACTED]
Sent: [REDACTED]
To: [REDACTED]
Subject: [EXTERNAL] IMPORTANT: Urgent Safety Recall

[View as a Web page](#)



Desplaza hacia abajo para español

**AVOID PUTTING YOURSELF AND YOUR LOVED
ONES IN DANGER.**



**DON'T IGNORE THIS
SAFETY RECALL**

Avoid putting yourself and your loved ones in danger.

In certain types of crashes, the front-seat side airbags and curtain shield airbags in your vehicle may not deploy properly, increasing the risk of injury.

Call **1-303-302-8888** to schedule your **FREE** repair.

Schedule service

What you need to know

CONDITION Certain 2015–2017 Model Year Yaris vehicles: The subject vehicles are equipped with side airbag sensors installed in each of the front doors and wire harnesses that connect these sensors to the airbag control unit. These wire harnesses could corrode over time, which could cause the airbag warning light to come on. In addition, the front-seat side airbags and curtain shield airbags could be deactivated or not deploy properly. **Non-deployment or improper deployment of these airbags can increase the risk of injury in the event of a crash.**

REMEDY Based on production records, any authorized Toyota dealer will replace the wire harness assembly in one or both doors, as necessary, with an improved one **FREE OF CHARGE**.

DURATION The remedy will take approximately one and a half hours. However, depending on the dealer's work schedule, it may be necessary to make your vehicle available for a longer period of time.

If you are not the current owner of the vehicle, [click here](#) to update your records.

EVITA PONER EN PELIGRO A TUS SERES QUERIDOS Y A TI MISMO

Los vehículos indicados están equipados con sensores de bolsas de aire laterales instalados en cada una de las puertas delanteras y arneses de cableado que conectan estos sensores con la unidad de control de la bolsa de aire. Estos arneses de cableado podrían corroerse con el tiempo, lo que podría hacer que se encienda la luz de advertencia de la bolsa de aire. Además, las bolsas de aire laterales de los asientos delanteros y las bolsas de aire tipo cortina podrían desactivarse o no desplegarse correctamente. **La falta de despliegue o el despliegue inadecuado de estas bolsas de aire pueden aumentar el riesgo de lesiones en caso de un choque.**

LLAMA AL [1-303-302-8888](tel:1-303-302-8888) PARA PROGRAMAR TU REPARACIÓN GRATUITA.



Service Center

It's easy to schedule the FREE safety recall repair with us

Set up your repair appointment with your local dealership.

Schedule today

Mountain States Toyota

201 West 70th Avenue
Denver, CO 80221
1-303-302-8888



Get directions ►

Service Center Hours

Mon: 7:00 am to 6:00 pm
Tue: 7:00 am to 6:00 pm
Wed: 7:00 am to 6:00 pm
Thu: 7:00 am to 6:00 pm
Fri: 7:00 am to 6:00 pm
Sat: 8:00 am to 5:00 pm
Sun: Closed

View dealer website ►

Services

- Parts Center
- Toyota Tire Center

Download the Toyota app



Vehicles shown may be prototypes, shown using visual effects and/or shown with options.

App Store is a service mark of Apple Inc.

Google Play and the Google Play logo are trademarks of Google LLC.

Please do not reply to this email. This is a post-only, outbound email.

You have received this communication because, according to state motor vehicle registration records, you are the owner of the Toyota vehicle with a Safety Recall that has not been repaired.

If you would like to update your owner information, please visit: toyota.com/owners

This email was sent by:
Mountain States Toyota
201 West 70th Avenue
Denver, CO 80221

