

IMPORTANT SAFETY RECALL

This INTERIM notice applies to your vehicle, VIN: Timing Chain Idler Gear NHTSA Recall #19V821 Mercedes-Benz USA, LLC

Christian Treiber Vice President Customer Services

January, 2020



Dear Mercedes-Benz Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has decided that a defect which relates to motor vehicle safety exists in certain Model Year ("MY") 2018-2019 S-Class vehicles. Our records indicate that your vehicle is included in the affected population of vehicles.

What is the Concern?

MBAG has determined that on certain MY 18-19 S-Class (222 platform) and S-Class Cabrio (217 platform) vehicles equipped with an 8-cylinder gasoline engine (M176), the threaded connection of the idler gear timing chain to the crankcase might not meet current production specifications. A threaded connection that does not meet current production specifications could result in the idler gear detaching from the crankcase. This detachment could lead to contact between the engine valves and the pistons, damaging the engine and leading to a vehicle stall, increasing the risk of a crash.

To remedy this issue, as a precautionary measure, an authorized Mercedes-Benz dealer will replace the engine on the affected vehicles. Unfortunately, the parts to remedy this are currently not yet available.

We are working to obtain the necessary parts to correct this condition as quickly as possible. As parts become available, we will send you another letter asking you to take your vehicle to an authorized Mercedes-Benz dealer to have the recall completed free of charge.

Should you have any concerns or questions regarding your vehicle before you receive the next recall letter when parts are available, please contact an authorized Mercedes-Benz dealer. If for any reason a dealer is unable to remedy your situation, we are always happy to hear from you. Please contact us at 1-800-367-6372. A new vehicle identification number (VIN)-based recall lookup tool, on our MBUSA.com website, now offers a search function that will indicate whether a vehicle has been subject to a safety recall, and whether that vehicle has had the free remedy performed. Please visit www.MBUSA.com/recall.

If you are no longer the vehicle owner, or have a change of address, please complete the reverse side of this letter and return the complete letter in the enclosed envelope. If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 days to comply with federal regulations.

If a Mercedes-Benz dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to http://www.safercar.gov.

We regret any inconvenience this situation may cause you.

Sincerely,

The trust

Mercedes-Benz USA, LLC A Mercedes-Benz AG Company

IM	PO	RT	Δ	N٦	Г

VIN:

☐ EXPORTED ☐ LEASE, VEHICLE RETURNED ☐ SCRAPPED											STOLEN																		
☐ NEW OWNER INFORMATION												MY NEW NAME OR ADDRESS IS:																	
																													T
Last	Nan	ne, Fi	rst N	lame								1		-1			-1				1		1	ı		-			
Stre	et			ı																	1		1	ı		Α	pt		
City				ı			1							1				1		1		St	ate		ZI	P			
																													Π
Ema	l Ad	dress	3		<u> </u>							1	1		1	1			1		-								
	l							1	1	1	1		1		1						1						Г	T	Т

THANK YOU FOR YOUR COOPERATION

Signature

Date