



6555 Katella Avenue • Cypress • California • 90630-5101 • (714) 761-7300 • Fax (714) 229-7944

April 30, 2019

Chief Administrator
National Highway Traffic Safety Administration
Associate Administrator for Safety Assurance (NVS-215)
1200 New Jersey Avenue SE
Washington DC 20590

Regarding: Certain 2019-Model YZF-R3, Lever #2 (Front Brake Lever) Inspection and / or Replacement, Factory Modification Campaign.

Dear Sir/Madam:

The purpose of this correspondence is to provide preliminary information required by 49 CFR 573 and the National Traffic and Motor Vehicle Safety Act regarding a defect notification campaign we are initiating. Provided via the recall portal are draft copies of the Owner's notification letter, for Agency approval, and the dealer technical bulletin. The envelope format and label has previously been approved by the Agency for prior campaigns.

1. Manufacturer's Name: Yamaha Indonesia Motor Manufacturing
JL. DR. KRT. Rajiman Widyodiningrat
Pulo Gadung, Jakarta 13920. Indonesia

Imported Vehicle Distributor: Yamaha Motor Corporation, U.S.A.
6555 Katella Avenue
Cypress, California 90630
2. Vehicles Affected: Make: Yamaha
 Model: YZF-R3 and YZF-R3 ABS Motorcycles
 Years: 2019

Nominal Engine Displacement: The YZF-R3 is 320cc

Production Period: Affected models were produced between
02/06/2019 – 03/06/2019
3. The campaign addresses the Lever #2 (front brake lever). The Lever for the front brake could break because it was improperly manufactured with possible porosities in the material. If Lever #2 breaks, it could be difficult to apply the front brakes.
4. Total number of subject vehicles: Current estimate: 198 units. This will be updated in a supplemental report as we finalize the affected VIN range.

5. VIN Range: Tentative range will be supplied in forthcoming draft Technical Bulletin. Likewise, this will be updated in a subsequent report as data is confirmed.
6. The campaign involves the inspection of the manufacturing date code stamped into the underside of the front brake lever and, if it is an affected date code, replacement of the lever with a new one. Please refer to the draft Technical Bulletin which will be furnished to the Agency and Yamaha dealers upon completion describing the situation which is the subject of the campaign.
7. April 22, 2019, Yamaha Motor Corporation, U.S.A. was informed by the manufacturer, Yamaha Indonesia Motor Manufacturing, that such a situation exists. This was determined pursuant to a quality control review, testing and a review of foreign models that use a substantially similar part design.

We anticipate commencing dealer/owner notification shortly after the owner's notification letter is approved by NHTSA (draft copies of the Customer Notification Letter and Technical Bulletin are attached for your review), the affected VIN range is ascertained, and the Technical Bulletin service procedure is confirmed and finalized by Yamaha service staff. Assuming the Agency can approve the letter within 5 days of receipt (perhaps May 06) we will have the letter and Technical Bulletin printed. Normal turn-around time is 3 working days for such printing. Hence the materials will be ready for mailing approximately May 09. Final copies of these notification documents will be forwarded to the Agency as soon as possible.

In the event we can answer any questions or provide supplemental information, please do not hesitate to contact me. My direct telephone number is 714-761-7842. The fax number is 714-229-7944. My email is brad_franklin@yamaha-motor.com.

Sincerely,

Bradley Franklin

Bradley Franklin
Division Manager, Certification and
Government Relations

BRF/lf