

SAFETY RECALL N333 DRIVER SEAT BELT EMERGENCY LOCKING RETRACTOR USA AND CANADA



RECALL N333 - DRIVER SEAT BELT EMERGENCY LOCKING RETRACTOR	
AFFECTED MODELS	16 &17 MY RANGE ROVER RANGE ROVER SPORT
USA VOLUME AFFECTED	16,186
REPAIR	INSPECT/REPLACE DRIVER SEAT BELT ASSEMBLY
REPAIR TIME	0.1HRS INSPECTION 0.3 HRS INSPECTION + REPAIR
REPAIR LAUNCHED	August 20, 2019
CUSTOMER NOTIFICATION BY MAIL	JULY 1ST 2019 RE- MAILED SEPT 10 TH 2019



Vehicles with ebony seatbelts only: inspect both sides of the front left seatbelt label for the production date and part number.

- If the front left seatbelt part number is 'CPLA 611B09ED8PVJ' and the production date is from 07/05/2016 up to and including 15/09/2016, go to step 5.
- If the front left seatbelt part number is 'CPLA 611B09ED8PVJ' but the production date is not from 07/05/2016 up to and including 15/09/2016, release the vehicle.



Vehicles with espresso seatbelts only: visually inspect both sides of the front left seatbelt label for the production date and part number.

- If the front left seatbelt part number is 'CPLA 611B09ED8AAM' and the production date is from 07/05/2016 up to and including 13/09/2016, go to step 5.
- If the front left seatbelt part number is 'CPLA 611B09ED8AAM' but the production date is not from 07/05/2016 up to and including 13/09/2016, release the vehicle.

Important note: Only belts with the exact part number shown in the repair bulletin and highlighted above are to be replaced.