

Recall Update February 7th

Recall 19V-692: K48/K61 (K 1600 B, GT, GTL):

The tools required for this recall campaign have been shipped to all dealers as of last week.

To simplify the distribution of the multiple parts required, the RDC is consolidating the components into kits. Kits are now shipping from the warehouse daily.

Dealers should continue to request kits for urgent cases by submitting an IDS ticket to Parts Logistics US -> Parts Consultant Group -> Motorrad Group Only Answered Inquiries with part number 81925A1BB87. All request for urgent cases must include a valid VIN number and short summary (customer bike, sold unit, etc.). Please do not place orders for the kit at this time as this will delay the allocation process. This process will remain in place until sufficient inventory arrives for parts to be opened up for standard dealer ordering.

Repair Tips:

1. When looking up repair instructions for the removal and installation of the transmission in AIR please make sure to enter the VIN of the vehicle. This ensures the correct instructions are displayed (with or without reverser).

2. For vehicles with reverser, two additional tools are needed. These tools were required tools for the K48/K61 and should be at your dealership. [Tool 23 0 817 (SI 06 001 14) part number 83 30 2 353 303, Tool 23 0 840 (SI 06 001 18) part number 83 30 2 450 826]. Tool 23 0 840 was auto shipped in October 2018. Please order these tools if you do not have them.

Important Reminder: Parts for all recalls should be utilized to meet customer repair demands before any inventory unit is repaired.