



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

August 26, 2020

Ms. Mei Ling Ding
Tong Yang Industry Co.
No. 98, Section 2, An Ho Road,
An Nan Dist., Tainan 70967

NEF-150KL
20E-056

Subject: Grille Moulding May Affect Cruise Control

Dear Ms. Ding:

This letter serves to acknowledge Tong Yang Industry Co.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

TONG YANG INDUSTRY/GRILLE MOULDING/9999

Mfr's Report Date: August 19, 2020

NHTSA Campaign Number: 20E-056

Components:

STRUCTURE:BODY

Potential Number of Units Affected: 105

Problem Description:

Tong Yang Industry Co. (Tong Yang) is recalling certain Grille Mouldings, part number HD07251MB, sold for aftermarket installation on 2019-2020 Honda HR-V vehicles. The grille moulding coating may prevent the radar sensor for the Adaptive Cruise Control (ACC), located behind the front grille, from functioning properly.

Consequence:

If the sensor of the ACC cannot not function properly, the vehicle may accelerate or decelerate inappropriately when using ACC, increasing risk of crash.

Remedy:

Tong Yang will notify their distributors. Tong Yang will reimburse customers for replacement parts and installation costs. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Tong Yang Service by calling 1-972-542-5378 or emailing danielt@taiplusllc.com.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:




Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kristin Lepper who may be reached by phone at 202-366-5227, or by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,



Joshua Neff
Chief, Recall Management Division
Office of Defects Investigations
Enforcement