

**Recall Quarterly Report****20E-064**

**Manufacturer Name :** Tenneco Automotive  
**NHTSA Recall No. / MFR Recall No. :** 20E-064 /  
**Recall Subject :** Master Cylinder Has Insufficient Fluid Seal Crimp  
**Owner Notification Beginning Date :** OCT 30, 2020  
**Owner Notification End Date:** OCT 30, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	OCT 30, 2021	2021-3	38	9	0	0
3	JUL 30, 2021	2021-2	38	9	0	0
2	APR 29, 2021	2021-1	38	9	0	0
1	JAN 30, 2021	2020-4	38	9	0	0

This Document Last Updated : NOV 01, 2021

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.