

Recall Quarterly Report

20V-150

Manufacturer Name : Triumph Motorcycles America, Ltd.
NHTSA Recall No. / MFR Recall No. : 20V-150 /SRAN574
Recall Subject : Front Brake Hose may be Improperly Routed
Owner Notification Beginning Date : APR 13, 2020
Owner Notification End Date: APR 13, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	APR 13, 2021	2021-1	1,585	492	0	0
3	JAN 19, 2021	2020-4	1,585	438	0	0
2	OCT 09, 2020	2020-3	1,585	332	0	0
1	JUL 09, 2020	2020-2	1,585	194	0	0

This Document Last Updated : APR 16, 2021

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.