

Recall Quarterly Report**20V-226**

Manufacturer Name : Mercedes-Benz USA, LLC
NHTSA Recall No. / MFR Recall No. : 20V-226 /2020050009
Recall Subject : Rear Seat Wiring Harness May Be Routed Incorrectly
Owner Notification Beginning Date : JUN 04, 2020
Owner Notification End Date: JUN 04, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
8	APR 22, 2022	2022-1	120	117	0	0
7	JAN 12, 2022	2021-4	120	116	0	0
6	OCT 19, 2021	2021-3	120	116	0	0
5	JUL 14, 2021	2021-2	120	115	0	0
4	APR 20, 2021	2021-1	120	107	0	0
3	JAN 14, 2021	2020-4	120	95	0	0
2	OCT 19, 2020	2020-3	120	76	0	0
1	JUL 16, 2020	2020-2	120	28	0	0

This Document Last Updated : MAY 02, 2022

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.