

Recall Quarterly Report**20V-329**

Manufacturer Name : Mercedes-Benz USA, LLC
NHTSA Recall No. / MFR Recall No. : 20V-329 /2020090001
Recall Subject : Shock Absorbers May Wear Prematurely
Owner Notification Beginning Date : OCT 20, 2020
Owner Notification End Date: OCT 20, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
8	OCT 21, 2022	2022-3	38	38	0	0
7	JUL 13, 2022	2022-2	38	38	0	0
6	APR 22, 2022	2022-1	38	38	0	0
5	JAN 11, 2022	2021-4	38	38	0	0
4	OCT 19, 2021	2021-3	38	38	0	0
3	JUL 14, 2021	2021-2	38	38	0	0
2	APR 19, 2021	2021-1	38	35	0	0
1	JAN 13, 2021	2020-4	38	24	0	0

This Document Last Updated : OCT 27, 2022

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.