

Recall Quarterly Report**20V-539**

Manufacturer Name : Daimler Trucks North America, LLC
NHTSA Recall No. / MFR Recall No. : 20V-539 /FL-862
Recall Subject : Lower Rear Pivot Cap Screws May Be Too Short
Owner Notification Beginning Date : OCT 30, 2020
Owner Notification End Date: OCT 30, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
8	OCT 27, 2022	2022-3	103	81	0	0
7	JUL 26, 2022	2022-2	103	81	0	0
6	APR 26, 2022	2022-1	103	79	0	0
5	JAN 27, 2022	2021-4	103	74	0	0
4	OCT 21, 2021	2021-3	103	71	0	0
3	JUL 28, 2021	2021-2	103	63	0	0
2	APR 14, 2021	2021-1	103	44	0	0
1	JAN 22, 2021	2020-4	103	22	0	0

This Document Last Updated : OCT 31, 2022

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.