

**Recall Quarterly Report****20V-627**

**Manufacturer Name :** Mercedes-Benz USA, LLC  
**NHTSA Recall No. / MFR Recall No. :** 20V-627 /2020100020  
**Recall Subject :** Locking Ring Connection on Drive Shaft May Fail  
**Owner Notification Beginning Date :** DEC 08, 2020  
**Owner Notification End Date:** DEC 11, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	APR 19, 2021	2021-1	2	2	0	0
1	JAN 13, 2021	2020-4	2	2	0	0

This Document Last Updated : APR 20, 2021

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.