

**Recall Quarterly Report****20V-651****Manufacturer Name :** Mercedes-Benz USA, LLC**NHTSA Recall No. / MFR Recall No. :** 20V-651 /2020110012**Recall Subject :** Damaged Power Steering Control Unit Wiring Harness**Owner Notification Beginning Date :** DEC 11, 2020**Owner Notification End Date:** DEC 11, 2020

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
8	OCT 20, 2022	2022-3	2,533	2,389	0	0
7	JUL 13, 2022	2022-2	2,533	2,370	0	0
6	APR 20, 2022	2022-1	2,533	2,346	0	0
5	JAN 11, 2022	2021-4	2,533	2,309	0	0
4	OCT 18, 2021	2021-3	2,533	2,264	0	0
3	JUL 14, 2021	2021-2	2,533	2,123	0	0
2	APR 19, 2021	2021-1	2,533	1,854	0	0
1	JAN 13, 2021	2020-4	2,533	630	0	0

This Document Last Updated : OCT 26, 2022

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.