

# Recall Quarterly Report

## 20V-709

**Manufacturer Name :** Tesla, Inc.

**NHTSA Recall No. / MFR Recall No. :** 20V-709 /SB-20-31-012

**Recall Subject :** Loose Control Arm Bolts May Affect Steering

**Owner Notification Beginning Date :** JAN 15, 2021

**Owner Notification End Date:** JAN 15, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
6	JUL 26, 2022	2022-2	401	351	0	0
5	APR 29, 2022	2022-1	401	348	0	0
4	JAN 31, 2022	2021-4	401	341	0	0
3	OCT 30, 2021	2021-3	401	334	0	0
2	JUL 29, 2021	2021-2	401	327	0	0
1	APR 30, 2021	2021-1	401	314	0	0

This Document Last Updated : AUG 01, 2022

### Definitions :

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.