

Recall Quarterly Report

20V-709

Manufacturer Name : Tesla, Inc.

NHTSA Recall No. / MFR Recall No. : 20V-709 /SB-20-31-012

Recall Subject : Loose Control Arm Bolts May Affect Steering

Owner Notification Beginning Date : JAN 15, 2021

Owner Notification End Date: JAN 15, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	JAN 31, 2022	2021-4	401	341	0	0
3	OCT 30, 2021	2021-3	401	334	0	0
2	JUL 29, 2021	2021-2	401	327	0	0
1	APR 30, 2021	2021-1	401	314	0	0

This Document Last Updated : FEB 01, 2022

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.