

**Recall Quarterly Report****20V-768****Manufacturer Name :** Honda (American Honda Motor Co.)**NHTSA Recall No. / MFR Recall No. :** 20V-768 /P9D**Recall Subject :** Driver Side Power Window Switch May Fail**Owner Notification Beginning Date :** JAN 29, 2021**Owner Notification End Date:** JAN 29, 2021

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
5	APR 21, 2022	2022-1	268,655	54,447	9,090	58,215
4	JAN 13, 2022	2021-4	268,655	51,679	9,208	57,924
3	OCT 13, 2021	2021-3	268,655	47,586	9,353	57,552
2	JUL 16, 2021	2021-2	268,655	41,444	9,541	55,852
1	APR 16, 2021	2021-1	268,655	30,364	786	54,045

This Document Last Updated : APR 26, 2022

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.