

Recall Quarterly Report**20V-778**

Manufacturer Name : Yamaha Motor Corporation, USA
NHTSA Recall No. / MFR Recall No. : 20V-778 /
Recall Subject : Improperly Torqued Slide Pins On Brake Caliper
Owner Notification Beginning Date : JAN 06, 2021
Owner Notification End Date: JAN 08, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	JAN 10, 2022	2021-4	1,375	432	0	0
3	OCT 01, 2021	2021-3	1,375	396	0	0
2	JUL 01, 2021	2021-2	1,375	337	0	0
1	APR 01, 2021	2021-1	1,375	239	0	0

This Document Last Updated : JAN 12, 2022

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.