

**Recall Quarterly Report****20V-778**

**Manufacturer Name :** Yamaha Motor Corporation, USA  
**NHTSA Recall No. / MFR Recall No. :** 20V-778 /  
**Recall Subject :** Improperly Torqued Slide Pins On Brake Caliper  
**Owner Notification Beginning Date :** JAN 06, 2021  
**Owner Notification End Date:** JAN 08, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
7	OCT 03, 2022	2022-3	1,375	484	0	0
6	JUL 05, 2022	2022-2	1,375	472	0	0
5	APR 01, 2022	2022-1	1,375	463	0	0
4	JAN 10, 2022	2021-4	1,375	432	0	0
3	OCT 01, 2021	2021-3	1,375	396	0	0
2	JUL 01, 2021	2021-2	1,375	337	0	0
1	APR 01, 2021	2021-1	1,375	239	0	0

This Document Last Updated : OCT 04, 2022

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.