

# Part 573 Safety Recall Report

# 20E-056

**Manufacturer Name :** Tong Yang Industry Co.

**Submission Date :** AUG 19, 2020

**NHTSA Recall No. :** 20E-056

**Manufacturer Recall No. :** NR



## Manufacturer Information :

**Manufacturer Name :** Tong Yang Industry Co.

**Address :** 98 An Ho Road Sec 2

Tainan 00 70967

**Company phone :** 99999

## Population :

**Number of potentially involved :** 105

**Estimated percentage with defect :** 100 %

## Equipment Information :

**Brand / Trade 1 :** Aftermarket

**Model :** Grille Moulding

**Part No. :** HD07251MB

**Size :** NR

**Function :** NR

**Descriptive Information :** Notified that the coating on the grille moulding's sold as aftermarket replacement parts for the Honda HR-V EX/EX-L/Touring Models 2019-2020 may interfere with the function of the Adaptive Cruise Control's radar sensor inside the front grille which could affect how the vehicle accelerates or decelerates.

**Production Dates :** DEC 18, 2019 - JUL 15, 2020

## Description of Defect :

**Description of the Defect :** The coating on grille moulding may prevent the radar sensor which is inside the front grille as part of the Adaptive Cruise Control from functioning properly to maintain, accelerate, decelerate, or stop.

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** If the sensor of the Adaptive Cruise Control (ACC) does not function properly, the ACC may not sense changes and lead to possible acceleration or deceleration.

**Description of the Cause :** NR

**Identification of Any Warning that can Occur :** NR

## Involved Components :

Component Name : NR

Component Description : NR

Component Part Number : NR

## Supplier Identification :

### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

## Chronology :

On July 28th, 2020, Tong Yang was notified that the radar cruise control stopped working after the grille moulding was installed and began its investigation. On July 30th, Tong Yang made the decision to recall all 105 parts that had been sold based on available information.

## Description of Remedy :

Description of Remedy Program : Tong Yang has notified its distributors and asked them to return the recalled parts in their inventory and for the distributors to contact their customers to identify the limited number of vehicles that the parts were installed on. Tong Yang will reimburse for replacement parts and installation costs.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : Current production of the parts ceased and the coating on the grille moulding will be changed if any future production..

## Recall Schedule :

Description of Recall Schedule : Tong Yang has notified direct customers (distributors) about the recall and requested that the distributors notify their customers to notify end users (owners) about the recall.

Planned Dealer Notification Date : AUG 18, 2020 - AUG 31, 2020

Planned Owner Notification Date : NR - NR

**Purchaser Information :**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

\* NR - Not Reported