

Part 573 Safety Recall Report**20V-161****Manufacturer Name :** Forest River, Inc.**Submission Date :** MAR 19, 2020**NHTSA Recall No. :** 20V-161**Manufacturer Recall No. :** 51-1152**Manufacturer Information :**

Manufacturer Name : Forest River, Inc.

Address : 55470 CR 1

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

Population :

Number of potentially involved : 51

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2019-2020 Forest River Inc. Berkshire and Sportscoach

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Per DTNA's Recall 20V-127 - Certain vehicles equipped with air disc brakes with incomplete production caliper torque data manufactured at the York Axle Manufacturing Plant.

US

BERKHIRE	BEA34QS-360	2019	2
BERKHIRE	BEA34QS-360	2020	3
BERKHIRE	BEA37A-380	2019	1
BERKHIRE	BEA37A-380	2020	1
BERKHIRE	BEA38A-360	2019	2
BERKHIRE	BEA39A-360	2019	1
BERKHIRE	BEA39B-360	2019	2
BERKHIRE	BEA40C-380	2019	4
BERKHIRE	BEA40C-380	2020	2
BERKHIRE	BEA40D-380	2019	2
BERKHIRE	BEA40D-380	2020	4
BERKHIRE	BEA45A-450	2019	10
BERKHIRE	BEA45B-450	2019	4
BERKHIRE	BEA45B-450	2020	1
SPORTSCOACH	S1A404RB-360	2019	3
SPORTSCOACHS1A404RB-360		2020	1
SPORTSCOACHS1A407FW-360		2019	4
SPORTSCOACHS1A407FW-360		2020	2
SPORTSCOACHS1A409BG-360		2019	2
Grand Total			51

Production Dates : NOV 20, 2018 - SEP 16, 2019

VIN Range 1 : Begin : NR

End : NR

 Not sequential

Description of Defect :

Description of the Defect : On certain vehicles, the brake caliper mounting bolts may be incorrectly torqued. This could result in caliper bolts loosening.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash.

Description of the Cause : Not Reported

Identification of Any Warning that can Occur : Not Reported

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

On March 18th , 2020 Forest Rivers Office of Corporate Compliance received Recall Notice 20V127 from DTNA.

On March 19th , 2020 Forest Rivers Office of Corporate Compliance was able to identify all vehicles affected

On March 19th , 2020 Forest River filed a Pass Thru Recall with NHTSA and Trans Canada

DTNA will provide NHTSA and Trans Canada with quarterly reporting

Description of Remedy :

Description of Remedy Program : Potentially affected vehicles will be inspected and repaired as necessary. Repairs will be performed by Daimler Trucks North America authorized service facilities. Details of the reimbursement plan will be included in the owner's notification letter.

What is DTNA's Customer Service Phone Number? 800-745-8000

How Remedy Component Differs from Recalled Component : Not Reported

Identify How/When Recall Condition was Corrected in Production : Not Reported

Recall Schedule :

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : APR 28, 2020 - APR 28, 2020

Planned Owner Notification Date : APR 28, 2020 - APR 28, 2020

* NR - Not Reported