

Part 573 Safety Recall Report

20V-296

Manufacturer Name : KZRV, L.P.**Submission Date :** MAY 22, 2020**NHTSA Recall No. :** 20V-296**Manufacturer Recall No. :** KZ-2020-02**Manufacturer Information :**

Manufacturer Name : KZRV, L.P.

Address : 0985 N 900W

Shipshewana IN 46565

Company phone : 800-768-4016x154/153

Population :

Number of potentially involved : 16

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2018 KZ RV Escape

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : The Population affected only one model of the Escape Product Line. The model is E180QB. The production range determined the population.

Production Dates : NOV 02, 2017 - FEB 21, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Noncompliance :**

Description of the Noncompliance : The vehicles subject to this recall have been manufactured with the incorrect information on the Federal Identification Tag and Tire Inflation Pressure Label. The labels indicate a Gross Axle Weight Rating (GAWR) of 5,000 lbs., a tire size of ST225/75R15E, a rim size of 15X6J, and an tire inflation pressure of 80 psi. The correct labels should indicate a Gross Axle Weight Rating (GAWR) of 3,500 lbs., a tire size of ST205/75R14D, a rim size of 14X5.5J, and an tire inflation pressure of 65 psi.

FMVSS 1 : 110 - Tire selection and rims

FMVSS 2 : NR

Description of the Safety Risk : The incorrect information on the labels could lead to an over inflation of the tires resulting in a crash.

Description of the Cause : The vehicle model database used to generate the labels contained the wrong information.

Identification of Any Warning that can Occur : None

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

5-15-2020- Service receives a request for a corrected Tire Placard from a Dealer. Engineering is notified to investigate these requests.

5-18-2020- Engineering confirms discrepancy and requests confirmation from dealer.

5-20-2020 - Information received verifying the label non-compliance. Safety Committee determines a recall is required.

Description of Remedy :

Description of Remedy Program : Corrected labels will be sent to owners for installation.

How Remedy Component Differs from Recalled Component : Labels have the correct vehicle information.

Identify How/When Recall Condition was Corrected in Production : This only affected one model year so it was corrected at model year change.

Recall Schedule :

Description of Recall Schedule : Letters will be sent to owners and dealers once approval is obtained from NHTSA.

Planned Dealer Notification Date : JUN 30, 2020 - JUN 30, 2020

Planned Owner Notification Date : JUN 30, 2020 - JUN 30, 2020

* NR - Not Reported