

# Part 573 Safety Recall Report

## 20V-532

**Manufacturer Name :** Gulf Stream Coach, Inc.**Submission Date :** SEP 02, 2020**NHTSA Recall No. :** 20V-532**Manufacturer Recall No. :** 08312020**Manufacturer Information :****Population :****Manufacturer Name :** Gulf Stream Coach, Inc.**Number of potentially involved :** 90**Address :** P. O. Box 1005  
503 S. Oakland Avenue Nappanee IN  
46550**Estimated percentage with defect :** 100 %**Company phone :** 999-999-9999**Vehicle Information :****Vehicle 1 :** 2021-2021 Enlighten 25BH**Vehicle Type :****Body Style :****Power Train :** NR

**Descriptive Information :** On 90 25BH Enlighten Travel Trailers manufactured by Gulf Stream Coach, Inc. ("GulfStream") the gas refrigerator compartment may not have been completely sealed from the interior living area of the travel trailer. During a quality control audit Gulf Stream Coach became aware of this production issue. The individual responsible for installing the refrigerator was not properly trained and had failed to complete the refrigerator installation as prescribed in the installation manual provided with the refrigerator. All travel trailers subject to this Recall and within the immediate control of "Gulfstream" have been repaired prior to releasing for shipment to Independent Dealerships.

**Production Dates :** JUL 16, 2020 - AUG 17, 2020**VIN Range 1 : Begin :** 1NL1G2721M6005000 **End :** 1NL1G2727M6005261 ☒ Not sequential**Description of Defect :**

**Description of the Defect :** On certain model 25BH Enlighten Travel Trailers manufactured by Gulf Stream Coach, Inc. ("GulfStream") the gas refrigerator compartment may not have been completely sealed from the interior living area of the travel trailer.

**FMVSS 1 :** NR**FMVSS 2 :** NR

**Description of the Safety Risk :** An Increased risk of carbon monoxide or flammable unburned Liquid Petroleum (LP) gases may migrate into the living quarters of the travel trailer if the refrigerator compartment is not properly sealed. Failure to provide adequate seals to the refrigerator compartment thus isolating the refrigerator

compartment from the living area of the travel trailer may increase the risk of fire, or carbon monoxide poisoning causing injury or death to occupants and/or damage to property.

Description of the Cause : NR

Identification of Any Warning  
that can Occur : NONE

### Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

### Supplier Identification :

#### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

### Chronology :

During a quality control audit Gulf Stream Coach became aware of this production issue. The individual responsible for installing the refrigerator was not properly trained and had failed to complete the refrigerator installation as prescribed in the installation manual provided with the refrigerator.

### Description of Remedy :

Description of Remedy Program : All identified travel trailers subject to this Recall will be required to be inspected and verified for proper seal of the refrigerator compartment in accordance to the work instructions which will be provided to the selling dealer or repair facility of the owner's preference for completing this Recall.

How Remedy Component Differs  
from Recalled Component :

NR

Identify How/When Recall Condition  
was Corrected in Production :

All travel trailers subject to this Recall and within the immediate control of "Gulfstream" have been repaired prior to releasing for shipment to Independent Dealerships.

### Recall Schedule :

Description of Recall Schedule :

Gulf Stream Coach, Inc. has the utmost urgency in our recalls. The defect notification, to be sent to the vehicles listed dealer and/or the current owner as soon as NHTSA provides an acknowledgement letter and subsequent RECALL number.

Planned Dealer Notification Date : SEP 14, 2020 - SEP 16, 2020

Planned Owner Notification Date : SEP 16, 2020 - SEP 18, 2020

\* NR - Not Reported