

# Part 573 Safety Recall Report

# 20V-777

**Manufacturer Name :** Altec Industries, Inc.

**Submission Date :** JUN 04, 2021

**NHTSA Recall No. :** 20V-777

**Manufacturer Recall No. :** CSN 789



## Manufacturer Information :

**Manufacturer Name :** Altec Industries, Inc.

**Address :** 210 Inverness Center Drive  
Birmingham AL 35242

**Company phone :** 205 991 7733

## Population :

**Number of potentially involved :** 183

**Estimated percentage with defect :** 70 %

## Vehicle Information :

**Vehicle 1 :** 2020-2020 Altec AN67-E100

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** The recall population was determined from a review of production records.

**Production Dates :** FEB 04, 2020 - NOV 19, 2020

**VIN Range 1 : Begin :** NR **End :** NR

Not sequential

## Description of Defect :

**Description of the Defect :** Valve was supplied from the supplier with a shuttle cartridge installed instead of a plug.

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** inadvertent boom movement could occur.

**Description of the Cause :** NR

**Identification of Any Warning that can Occur :** The defect could be detected during the preoperational inspection.

## Involved Components :

Component Name 1 : Shuttle Cartridge

Component Description : NR

Component Part Number : 035269239

## Supplier Identification :

### Component Manufacturer

Name : Parker Hannifan Corporation

Address : 203 Pine Street

Forest City North Carolina 28043

Country : United States

## Chronology :

The supplier conducted an investigation of a valve returned by Altec Service and found that a shuttle cartridge was installed in place of a plug. The supplier conducted an investigation of production valves to determine range of effected units.

There have been no reported incidents.

## Description of Remedy :

Description of Remedy Program : Parker will supply a replacement plug. Altec does not have a dealer network and issues letters to owners only.

How Remedy Component Differs from Recalled Component : A new plug replaces a shuttle cartridge.

Identify How/When Recall Condition was Corrected in Production : Parker identified the wrong component on November 19, 2020 in production and replaced the cartridge with the plug in all valves built after November 19, 2020.

## Recall Schedule :

Description of Recall Schedule : Altec will issue CSN 789 to owners of the affected units. Altec does not have a dealer network and issues letters to owners only.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : FEB 04, 2021 - FEB 05, 2021

\* NR - Not Reported