

Part 573 Safety Recall Report

20V-777

Manufacturer Name : Altec Industries, Inc.

Submission Date : DEC 11, 2020

NHTSA Recall No. : 20V-777

Manufacturer Recall No. : CSN 789



Manufacturer Information :

Manufacturer Name : Altec Industries, Inc.

Address : 210 Inverness Center Drive
Birmingham AL 35242

Company phone : 205 991 7733

Population :

Number of potentially involved : 183

Estimated percentage with defect : 70 %

Vehicle Information :

Vehicle 1 : 2020-2020 Altec AN67-E100

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined from a review of production records.

Production Dates : FEB 04, 2020 - NOV 19, 2020

VIN Range 1 : Begin : NR **End :** NR

Not sequential

Description of Defect :

Description of the Defect : Valve was supplied from the supplier with a shuttle cartridge installed instead of a plug.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : inadvertent boom movement could occur.

Description of the Cause : NR

Identification of Any Warning that can Occur : The defect could be detected during the preoperational inspection.

Involved Components :

Component Name 1 : Shuttle Cartridge

Component Description : NR

Component Part Number : 035269239

Supplier Identification :

Component Manufacturer

Name : Parker Hannifan Corporation

Address : 203 Pine Street

Forest City North Carolina 28043

Country : United States

Chronology :

The supplier conducted an investigation of a valve returned by Altec Service and found that a shuttle cartridge was installed in place of a plug. The supplier conducted an investigation of production valves to determine range of effected units.

There have been no reported incidents.

Description of Remedy :

Description of Remedy Program : Parker will supply a replacement plug. Altec does not have a dealer network and issues letters to owners only.

How Remedy Component Differs from Recalled Component : A new plug replaces a shuttle cartridge.

Identify How/When Recall Condition was Corrected in Production : Parker identified the wrong component on November 19, 2020 in production and replaced the cartridge with the plug in all valves built after November 19, 2020.

Recall Schedule :

Description of Recall Schedule : Altec will issue CSN 789 to owners of the affected units. Altec does not have a dealer network and issues letters to owners only.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : FEB 04, 2021 - FEB 05, 2021

* NR - Not Reported