

**Recall Annual Report****20V-150**

**Manufacturer Name :** Triumph Motorcycles America, Ltd.  
**NHTSA Recall No. / MFR Recall No. :** 20V-150 /SRAN574  
**Recall Subject :** Front Brake Hose may be Improperly Routed  
**Owner Notification Beginning Date :** APR 13, 2020  
**Owner Notification End Date:** APR 13, 2020

**Annual Reports**

Report #	Submission Date	Report Year	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JUL 14, 2023	2023	1,585	869	0	0

**Quarterly Reports**

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
8	APR 08, 2022	2022-1	1,585	683	0	0
7	JAN 11, 2022	2021-4	1,585	649	0	0
6	OCT 05, 2021	2021-3	1,585	590	0	0
5	JUL 09, 2021	2021-2	1,585	541	0	0
4	APR 13, 2021	2021-1	1,585	492	0	0
3	JAN 19, 2021	2020-4	1,585	438	0	0
2	OCT 09, 2020	2020-3	1,585	332	0	0
1	JUL 09, 2020	2020-2	1,585	194	0	0

This Document Last Updated : JUL 24, 2023

**Definitions :**

**Report Year :** The report year the manufacturer is reporting recall completion figures.

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.