

**Recall Annual Report****20V-539**

**Manufacturer Name :** Daimler Trucks North America, LLC  
**NHTSA Recall No. / MFR Recall No. :** 20V-539 /FL-862  
**Recall Subject :** Lower Rear Pivot Cap Screws May Be Too Short  
**Owner Notification Beginning Date :** OCT 30, 2020  
**Owner Notification End Date:** OCT 30, 2020

**Annual Reports**

Report #	Submission Date	Reporting Period	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	OCT 26, 2023	2022-4 to 2023-3	103	88	0	0

**Quarterly Reports**

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
8	OCT 27, 2022	2022-3	103	81	0	0
7	JUL 26, 2022	2022-2	103	81	0	0
6	APR 26, 2022	2022-1	103	79	0	0
5	JAN 27, 2022	2021-4	103	74	0	0
4	OCT 21, 2021	2021-3	103	71	0	0
3	JUL 28, 2021	2021-2	103	63	0	0
2	APR 14, 2021	2021-1	103	44	0	0
1	JAN 22, 2021	2020-4	103	22	0	0

This Document Last Updated : NOV 30, 2023

**Definitions :**

**Reporting Period:** The reporting period is the manufacturer is reporting recall completion figures.

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.