

# Recall Annual Report

# 20V709



U.S. Department  
of Transportation  
  
National Highway  
Traffic Safety  
Administration

**Manufacturer Name:** Tesla, Inc.**NHTSA Recall No. / MFR Recall No.:** 20V709 / SB-20-31-012**Recall Subject:** Loose Control Arm Bolts May Affect Steering**Owner Notification Beginning Date:** Jan 15, 2021

## Annual Reports

Report #	Submission Date	Update Date	Reporting Period	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	Jan 28, 2026	Jan 28, 2026	2025-1 to 2025-4	401	385	0	0
2	Feb 03, 2025	Feb 03, 2025	2024-1 to 2024-4	401	382	0	0
1	Jan 29, 2025	Jan 30, 2025	2023-1 to 2023-4	401	377	0	0

## Quarterly Reports

Report #	Submission Date	Update Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
8	Aug 25, 2023	Aug 28, 2023	2022-4	401	364	0	0
7	Oct 29, 2022	Nov 04, 2022	2022-3	401	359	0	0
6	Jul 26, 2022	Aug 01, 2022	2022-2	401	351	0	0
5	Apr 29, 2022	May 02, 2022	2022-1	401	348	0	0
4	Jan 31, 2022	Feb 01, 2022	2021-4	401	341	0	0
3	Oct 30, 2021	Nov 08, 2021	2021-3	401	334	0	0
2	Jul 29, 2021	Jul 29, 2021	2021-2	401	327	0	0
1	Apr 30, 2021	May 06, 2021	2021-1	401	314	0	0

This document last updated: Feb 04, 2026

### Definitions:

**Reporting Period:** The reporting period the manufacturer is reporting recall completion figures.

**Report Quarter:** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

**Recall Population:** The total number of products recalled by the manufacturer.

**Total Remedied:** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable:** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed:** Products that have been scrapped, stolen, or exported.

